

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Wildcat	7. Unit Agreement Name none
2. Name of Operator Cambern and Associates Oil and Gas	8. Farm or Lease Name Hill Ranch
3. Address of Operator Rt. 1, Box 501A, Amarillo, Texas 79106	9. Well No. 1
4. Location of Well UNIT LETTER <u>M</u> . <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>28</u> TOWNSHIP <u>31N</u> RANGE <u>3E</u> NMPM. <u>Proposed Martin/Borders</u> <u>12</u> <u>1S</u> <u>2E</u>	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 7866' KB	12. County Rio Arriba

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	
		OTHER _____ <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

10/23/87 - Spud 8 3/4" surface hole at 8:00 PM. Drilled to TD of 120'. Ran 116' of 7", 20#, J-55 casing, set at 120'. Cement with 30 sxs. of Cl. B with 3% CaCl.(35.4 cuft). Cement circ. to surface. WOC 12 hours. Test to 500 psi/ 30 mins.- OK.

RECEIVED  
APR 07 1988  
OIL CON. DIV.  
DIST. 3

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W.D. Stricklin TITLE Agent DATE 4/7/88

APPROVED BY Original Signed by FRANK T. CHAVEZ SUPERVISOR DISTRICT # 1 DATE APR 07 1988

CONDITIONS OF APPROVAL, IF ANY: