

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: September 30, 1990

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill, deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well: oil well _____ gas well _____ other ☒ X

2. Name of Operator: Blackwood & Nichols Co. A Limited Partnership

3. Address of Operator: P.O. Box 1237, Durango, CO 81302-1237

4. Location of Well: (Footage, Sec., T., R., M., or Survey Description)

555' FSL, 720' FWL - Section 11, T31N, R7W

5. Lease Designation & Serial #:

NM-03358

6. If Indian, Allottee/Tribe Name

7. If Unit or CA, Agmt. Design.:

Northeast Blanco Unit

8. Well Name and No.:

Middle Mesa SWD #2

9. API Well No.:

30-045-28553

10. Field & Pool/Expltry Area:

Wildcat/Morrison Entrada

11. County or Parish, State:

San Juan, New Mexico

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION	
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input checked="" type="checkbox"/> Other: SIDETRACK	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

On October 11, 1991 while drilling at 7451' (Mancos Shale) our drill pipe twisted off at approximately 3000 feet and at the same time backed out at 120 feet. This 2850 foot length of pipe fell down the hole beside the drill string. We have cleaned the well bore out to 4420 feet (in the Lewis Shale) and now plan to set an inflatable bridge plug on top of the fish, spot 200 feet of cement on top of the bridge plug and sidetrack the well bore. We plan to kick out to a maximum of 10' and let the hole come back to vertical so to be at least 120 feet away from the old well bore.

Wayne Townsend has given verbal approval to this procedure 11/06/91.

RECEIVED

NOV 22 1991

OIL CON. DIV.

DIST. 3

14. I hereby certify that the foregoing is true and correct.

Signed: AL RECTOR AL RECTOR

Title: DISTRICT SUPERINTENDENT

Date: 11/6/91

(This space for Federal or State office use)

Approved By _____ Title _____

Conditions of approval, if any:

APPROVED

Date: NOV 21 1991

AREA MANAGER