

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use  
"APPLICATION FOR PERMIT--" for such proposals

RECEIVED  
94 SEP -8 AM 10:23

SUBMIT IN TRIPLICATE

670 FARMINGTON, NM

1. Type of Well  
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator  
NORTHWEST PIPELINE CORP.

3. Address and Telephone No.  
PO BOX 58900 MS 2M3 SLC UTAH 84158-0900 (801)584-6981

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
963' FNL 1184' FWL SEC. 26, T31N, R6W

5. Lease Designation and Serial No.  
SF-078771

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation  
892000587 O

8. Well Name and No.  
ROSA UNIT #8A

9. API Well No.  
30-039-25430

10. Field and Pool, or Exploratory Area  
ROSA PICTURED CLIFFS  
BLANCO MESAVERDE

11. County or Parish, State  
RIO ARRIBA, NEW MEXICO

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment

☐ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☒ Other COMPLETION OPERATIONS

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion  
on Well Completion or Recompletion Report  
and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.  
If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

8-19-94  
Clean out to 5930'. Pressure test casing to 3300#, held OK. Perforated Point Lookout from 5563 to 5819 with 35 (0.36") holes.

8-20-94  
Fraced Point Lookout with 109,100# of 20/40 sand and 2538 bbls of slick water. Job completed at 0800 hrs 8/19/94. ISIP = 350#. ATP = 2000#, AIR = 68 BPM, MTP = 2480#, MIR = 72.7 BPM. Set CIBP at 5550' and pressure tested to 3300#. TIH and spotted 500 gals of 7-1/2% HCL. TOH. Perforated as follows: 5292', 95', 98', 5301', 04', 07', 28', 31', 50', 53', 56', 59', 62', 65', 68', 71', 74', 77', 80', 5406', 34', 50', 57', 96', 98', 5502', 04', 06', 12', 30'. Total of 30 (0.36") holes. Fraced Menefee/Cliff House with 53,500# of 20/40 sand and 1939 bbls of slick water. Well screened out. Job completed at 1545 hrs 8/19/94. ISIP = 150#. ATP = 1980#, AIR = 60 BPM, MTP = 3150#, MIR = 61.2 BPM. Set RBP at 3250'.

CONTINUED ON PAGE 2

14. I hereby certify that the foregoing is true and correct

Signed KATHY BARNEY

Title

Kathy Barney SR. OFFICE ASSISTANT Date 09/06/94

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

\*See Instruction on Reverse Side

1994  
FARMINGTON DISTRICT OFFICE  
BY Sm