## 30-039-26149 ROSA UNIT COM #169A, J-03-31N-06W

THE FOOTAGES FOR THIS WELL ARE NOT CORRECT IN THE PERMIT TO DRILL AND THE ORIGINAL PLAT. THE SURFACE FOOTAGES WERE CORRECTED TO 2375/S, 1750/W, AND THE BOTTOM HOLE LOCATION CORRECTED TO 1788/S, 1606/W, UNIT LETTER K, AND A NEW PLAT WAS RECEIVED FOR THIS WELL ON 08/13/1999.

THE ONGARD TABLES WERE CHANGED FOR THIS WELL BY MARY ELLEN VILLANUEVA ON 10/19/1999 TO REFLECT THE NEW LOCATION AND ELEVATION.