Form 9-881 a (Feb. 1951)						

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

	rippic	vveu.	
Land O	ffice.	lente	7e
Lease N	lo (778799)
Unit	Sen	Juan	31-5

NOTICE OF INTENTION TO CHANGE PLANS. NOTICE OF INTENTION TO TEST WATER SHUT-OFF. NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL NOTICE OF INTENTION TO SHOOT OR ACIDIZE. NOTICE OF INTENTION TO PULL OR ALTER CASING. NOTICE OF INTENTION TO ABANDON WELL NOTICE OF INTENTION TO ABANDON WELL NOTICE OF INTENTION TO ABANDON WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR SUBSEQUENT REPORT OF ABANDONMENT SUPPLEMENTARY WELL HISTORY OCT 1 1962		
Well No. 23 is located 1650 ft. from $\begin{bmatrix} N \\ M \end{bmatrix}$ line and 1550 ft. from $\begin{bmatrix} E \\ M \end{bmatrix}$ line of	EOLOGICAL SURVEY		
Ms Section 34 31-4 5-4 B.M.P.M. (3/ Sec. and Sec. No.)			
(Field) (County or Subdivision) (State or Territory) The elevation of the derrick floor above sea level is ft.	60		
DETAILS OF WORK (State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate musing points, and all other important proposed work)			
Spud date 9-8-52. On 9-9-62 T.D. 320'. Ran 10 jts. 9 5/8" 32.30# H-b0 (305') set at 318'. Commuted w/230 secks regular, 1/8 cu. ft. Strats-Crete"6"/sk., 25 HA-5, circulated to surface. Held 600#/30 minutes.	1/60° 3 1962		
I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be	1 Sommenced		
I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be Company E. Faso Satural Gas Company	commenced.		
Company El Paso Matural Gas Company	commenced.		
Company El Faso Matural Gas Company Address Box 990	s commenced.		
Company El Paso Matural Gas Company	······································		