

## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

	Approval expires 12-31-60.	*
Land	New Mexico	
	NM-C48574	-
	Pan American Gas Unit "A"	•
Cmit	Unit "A"	•

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF. 8 5/8"
NOTICE OF INTENTION TO CHANGE PLANS.	
	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.	11
NOTICE OF INTENTION TO PULL OR ALTER CASING	i 1.
NOTICE OF INTENTION TO ABANDON WELL.	
(INDICATE ABOVE BY CHECK MARK N	IATURE OF REPORT, NOTICE, OR OTHER DATA)
Pan A merican Gas Unit "A"	Farmington, New Mexico Harch 12, 19 62
Sw/4, SE/4, Section 31 T-30-N B-3 (1/4 Sec. and Sec. No.) (Twp.) (F	Range) (Meridian)
Flora Vista Hesaverde San Juan	New Mexico
(Field) (County or	Subdivision) (State or Territory)
·	S OF WORK
(State names of and expected depths to objective sands; show sizes ing points, and all oth	, weights, and lengths of proposed casings; indicate mudding jobs, cement- ter important proposed work)
with 200 sacks Theor cement containing	rch 8, 1962. 8 5/8" casing was set at 296 g 2% calcium chloride. Cement circulated. g with 400 psi for 30 minutes with no drop at 296' and resumed drilling.
	MAR1 4 1962  MAR1 5.1. COM.
I understand that this plan of work must receive approval in w	riting by the Geological Survey before operations, may be comprehed.
Company Pan American Petroleum Corpor	at1on
Address P. O. Box 480	CRECITERY Common
Farmington, New Mexico	By R. M. Bayer
Attn: L. O. Speer, Jr.	Title Senior Petroleum Engineer