
Form 9-331 a (Feb. 1951)



## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Santa Pe
Lease No	<b>JM</b> 03998
Unit	



## SUNDRY NOTICES AND REPORTS ON WELL\$15. 1962

	NTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFFIL S. GEGLOGICA	XX
OTICE OF INTE			- <del></del> .
01102 01 111121	NTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING GTGG, 115	<u> </u>
OTICE OF INTE	NTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
OTICE OF INTE	NTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
OTICE OF INTE	NTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
OTICE OF INTE	NTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
OTICE OF INTE	NTION TO ABANDON WELL		_
Trieb	Federal	ARTEC, HAY MEXICO, July 2,	
(% Sec. an	33 30 kg d Sec. No.) (Twp.)	ft. from S line and 1550 ft. from E line of sec	33.
Besin D		San Juan Hev Nextco (County or Subdivision) (State or Territory)	-
		DETAILS OF WORK	
8pudded	ing points	s; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, and all other important proposed work)	cement
Spudded Drilled surface 242.59'	6-24-62 245' of 13 3/4" surf pipe, 231.74' plus 1	Face hole; ram 85 jts., 9 5/8", H-h0, 32.30#1.25' bradenhead plus 9.60' to KB; landed at	cement
Spudded Drilled surface 242.59'	6-24-62 245' of 13 3/4" surf pipe, 231.74' plus 1 RB.	face hole; ram 85 jts., 9 5/8", H-40, 32.30# 1.25' bradenhead plus 9.60' to KB; landed at  nt, 25 CACL; good return; plug down	у.м. )
Spudded Brilled surface 242.59' Commutes 6-25-62:	ing points 6-24-62 245' of 13 3/4" suri pipe, 231.74' plus 1 18. 1 v/200 sex reg cemen	face hole; ram 85 jts., 9 5/8", H=40, 32.30# 1.25' brademised plus 9.60' to KB; landed at at, 25 CACL; good return; plug down  RELEVEL  JUL 5 196  pproval in writing by the Geological Survey before operations may be commended.	<b>P.M.</b>
Spudded Brilled surface 242.59' Commutes 6-25-62:	ing points 6-24-62 245' of 13 3/4" surf pipe, 231.74' plus 1 NB. 1 v/200 sex reg cemen	face hole; ram 85 jts., 9 5/8", H=40, 32.30# 1.25' brademised plus 9.60' to KB; landed at at, 25 CACL; good return; plug down  RELEVEL  JUL 5 196  pproval in writing by the Geological Survey before operations may be commended.	<b>?.m.</b> 2
Spudded Brilled surface 242.59' Committee 6-25-62:	ing points 6-24-62 245' of 13 3/4" suri pipe, 231.74' plus 1 18. 1 v/200 sex reg cemen	face hole; ram 85 jts., 9 5/8", H=40, 32.30# 1.25' brademised plus 9.60' to KB; landed at at, 25 CACL; good return; plug down  RELEVEL  JUL 5 196  pproval in writing by the Geological Survey before operations may be commended.	<b>P.M.</b>
Spudded  Brilaed surface 242.59' Communication 6-25-62	ing points 6-24-62 245' of 13 3/4" suri pipe, 231.74' plus 1 RB. 1 v/200 sex reg cemen	face hole; ram 85 jts., 9 5/8", H=40, 32.30# 1.25' brademised plus 9.60' to KB; landed at at, 25 CACL; good return; plug down  RELEVEL  JUL 5 196  pproval in writing by the Geological Survey before operations may be commended.	<b>?.м.</b> 2