

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-045-08958
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-6714
7. Lease Name or Unit Agreement Name O Henry
8. Well No. 1
9. Pool name or Wildcat Basin Fruitland Coal

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator Dugan Production Corp.	
3. Address of Operator P.O. Box 420, Farmington, NM 87499	
4. Well Location Unit Letter <u>N</u> : <u>790</u> Feet From The <u>South</u> Line and <u>1850</u> Feet From The <u>West</u> Line Section <u>36</u> Township <u>30N</u> Range <u>14W</u> NMPM San Juan County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 5566' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: OIL CON. DIV. ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: T.D., casing & cement ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

T.D. 1260' reached on 5-4-91.

T.I.H. with 6-1/4" bit & drill pipe. Circulate hole clean - 7' fill. Laid down drill pipe. T.I.H. with 29 jts. 4-1/2", 10.5#, J-55 casing landed at 1255', float collar at 1225'. Circulate hole. Pump 10 bbls water. Cement with 200 sx 2% lodense with 1/4# celloflake/sk, tail with 150 sx class "B" neat w/1/4# celloflake/sk. (Total cement slurry = 587 cu.ft.). Displace with 20 bbls water. Plug down 1:00 P.M. 5-5-91. 1000# held OK. Had good circulation throughout job. Circulate 20 bbls cement.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jim L. Jacobs TITLE Geologist DATE 5-6-91
TYPE OR PRINT NAME TELEPHONE NO.

(This space for State Use)

APPROVED BY Original Signed by FRANK T. CHAVEZ TITLE SUPERVISOR DISTRICT # 3 DATE MAY 07 1991

CONDITIONS OF APPROVAL, IF ANY: