


(SUBMIT IN TRIPLICATE)

Land Office SF 078619

Lease No. _____

Unit _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 26, 1957

Well No. 1 is located 680 ft. from SPX line and 980 ft. from E line of sec. 31

SE 1/4 Sec. 31 30N 14W NMFM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Wildcat San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5360 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

5 1/2" Casing pulled

Cement plug from 2950' to 2600'
Cement plug from 2400' to 1700'
Cement plug from 900' to 600'
Cement plug from 450' to surface

Marker set and location cleaned up



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Jay J. Harris

Address 801 Ridgcrest Drive, SE

Albuquerque, New Mexico

By Jay J. Harris
Jay J. Harris

Title Operator