

(SUBMIT IN TRIPLICATE)

Indian Agency Navajo

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Allottee \_\_\_\_\_

Lease No. 11-80-603-1045

SUNDRY NOTICES AND REPORTS ON WELLS

|   |  |                                     |
|---|--|-------------------------------------|
| NOTICE OF INTENTION TO DRILL                  | SUBSEQUENT REPORT OF WATER SHUT-OFF        |                                     |
| NOTICE OF INTENTION TO CHANGE PLANS           | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING |                                     |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF    | SUBSEQUENT REPORT OF ALTERING CASING       |                                     |
| NOTICE OF INTENTION TO REDRILL OR REPAIR WELL | SUBSEQUENT REPORT OF REDRILLING OR REPAIR  |                                     |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE       | SUBSEQUENT REPORT OF ABANDONMENT           | <input checked="" type="checkbox"/> |
| NOTICE OF INTENTION TO PULL OR ALTER CASING   | SUPPLEMENTARY WELL HISTORY                 |                                     |
| NOTICE OF INTENTION TO ABANDON WELL           |  |                                     |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 19, 19 62

**Core Hole**

Well No. 30 is located 729 ft. from N line and 656 ft. from E line of sec. 34

**NE NE Section 34**

(1/4 Sec. and Sec. No.)

**30N**

(Twp.)

**19W**

(Range)

**R4E**

(Meridian)

**Wildcat**

(Field)

**San Juan**

(County or Subdivision)

**New Mexico**

(State or Territory)


The elevation of the derrick floor above sea level is 5112' 00

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate main casing points, and all other important proposed work)

**TO 100'**

Well was plugged and abandoned as follows: 100' plug in surface which covers top of Gallup formation. A regulation dry hole marker was placed in top of cement. Location is clean and ready for inspection.



RECEIVED  
SEP 21 1962

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Humble Oil & Refining Company

Address P. O. Box 3082

Durango, Colorado

By COPY (ORIGINAL SIGNED) E. M. BRADLEY

Title Dist. Supt.