

(SUBMIT IN TRIPLICATE)

Indian Agency Navajo
Window Rock
Allottee _____
Lease No. 14-20-403-1045

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<input checked="" type="checkbox"/>		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 2, 19 62


Rattlesnake
Well No. 1 is located 760 ft. from N line and 1040 ft. from E line of sec. 34
SE/4 34 30N 19W RPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Rattlesnake San Juan County New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5140 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 10-17-62. Drilled 1 1/2" hole from 0 to 184'. Drilled 1 3/4" hole with air from 184' to 830'. Sample top of Dakota at 825'. Encountered fresh water in Dakota. Proposed to set cement plug from 730' to 830' and from 0' to 100'. Correct dry hole marker and abandon.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Marrell Budd
Address 1413 Camino Rio
Farmington, New Mexico
By Marrell Budd
Title _____