

Submit 3 Copies  
to Appropriate  
District Office

3 NMCCD

1 File

State of New Mexico

Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.

30 045 08998

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Julander

8. Well No.

2

9. Pool name or Wildcat

Fulcher Kutz, PC

1. Type of Well:

OIL  
WELL ☐

GAS  
WELL ☒

OTHER

2. Name of Operator

Dugan Production Corp.

3. Address of Operator

P.O. Box 420, Farmington, NM 87499

4. Well Location

Unit Letter I : 2320 Feet From The South Line and 330 Feet From The East Line

Section

33

Township

30 North Range 12 West

NMPM

San Juan

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

5773' GL

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: Check casing ☒

### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well is scheduled for plug and abandonment. There is an obstruction in the 7" casing at approximately 165'. The nature of this obstruction is unknown. Attempts to get past the blockage with a perforating gun and 1-1/4" tubing have failed. Operator plans to run a sand line drill to remove the obstruction. If this fails, we will consult with you about the next step. The well is located near a deep arroyo which prevents setting the anchors necessary to rig up a rig large enough to drill out anything in the hole. The shallow depth will limit the effectiveness of any drilling operation. While we recognize the need to properly plug this well, the ability to do so will depend on our ability to gain access to the wellbore. We will move a rig to location to run the sand line drill by 2/22/99. We will notify you prior to going to location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

John Alexander

TITLE Vice-President

DATE 2-3-99

TYPE OR PRINT NAME

John Alexander

TELEPHONE NO. 325-1821

(This space for State Use)

DEPUTY OIL & GAS INSPECTOR, DIST. #1

APPROVED BY

CHARLIE V. ARDEN

TITLE

DATE

FEB 1 1999

CONDITIONS OF APPROVAL, IF ANY: