

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Santa Fe**
Lease No. **078107**
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

| | |
|--|---|
| NOTICE OF INTENTION TO DRILL | SUBSEQUENT REPORT OF WATER SHUT-OFF |
| NOTICE OF INTENTION TO CHANGE PLANS | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF | SUBSEQUENT REPORT OF ALTERING CASING |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL | SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE | SUBSEQUENT REPORT OF ABANDONMENT |
| NOTICE OF INTENTION TO PULL OR ALTER CASING | SUPPLEMENTARY WELL HISTORY Completion Report X |
| NOTICE OF INTENTION TO ABANDON WELL | |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

N. M. Fed. "L"

7-5, 19**63**

Well No. **3** is located **1980** ft. from **S** line and **1980** ft. from **E** line of sec. **33**

NW/4 SE/4 Sec. 33
(1/4 Sec. and Sec. No.)

T30N
(Twp.)

R15W
(Range)

NMPM
(Meridian)

Undesignated
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is **5351'** ft.


DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Potential Test:
6-29-63

Pumped 18 BO, 0 BW, 53 MCF gas in 24 hrs., GOR 2950/1. Final Report.

U. S. GEOLOGICAL SURVEY
SANTA FE, NEW MEXICO



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Sunray DX Oil Company**

Address **200 Pet. Club Plaza**

Farmington, New Mexico

Original signature
CHARLES W. ROGERS

By _____

Title **Production Engineer**