
(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**



Forrest ell No. 1 is located 1650 ft. fr			August 25		•
(indicate above by check mari	NATURE OF				
OTICE OF INTENTION TO PULL OR ALTER CASING OTICE OF INTENTION TO ABANDON WELL		EMENTARY WELL			- 1
OTICE OF INTENTION TO SHOOT OR ACIDIZE	li li	QUENT REPORT O			1
OTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	il .	QUENT REPORT O			l l
OTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSE	QUENT REPORT O	F ALTERING CASI	NG	
OTICE OF INTENTION TO CHANGE PLANS	SUBSE	QUENT REPORT O	F SHOOTING OR	ACIDIZING	
OTICE OF INTENTION TO DRILL	SUBSE	QUENT REPORT O	F WATER SHUT-OF	F	

The elevation of the derrick floor above sea level is _____ ft. (CL)

(Twp.)

DETAILS OF WORK

(Range)

Sen Juan (County or Subdivision) N. M. P. M.

New Mexico

(State or Territory)

(Meridian)

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well Spudded: August 20, 1951

SM NE Sec. 35

(14 Sec. and Sec. No.)

Wildogs

(Field)

Set 100' of 9-5/8" surface casing. Comented with 65 sacks and coment sirculated to surface. Tested with 1,000 p.s.i. pressure for 30 minutes. He pressure drop, 30 min. test, Test made before and after drilling plue.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.				
Company	Marphy Corporation			
Address	Marphy Building	1000 2		
	El Dorade, Arkanese	By W. Thornton		
		Title Supt.		

State of the state