


Form 100-10
Rev. 1-55



(SUBMIT IN TRIPPLICATE)
**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

Field Office Santa Fe
Lesse No. 078385
Date 8/2 Sec. 35

SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	AUG 3 1962
NOTICE OF INTENTION TO CHANGE PLUG	SUBSEQUENT REPORT OF REDUCED OR ABANDONED	U. S. GEOLOGICAL SURVEY FARMINGTON, NEW MEXICO
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING Casing	
NOTICE OF INTENTION TO REPAIR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO CEMENT OR ABANDON	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PUMP OR ALTER Casing	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(CHECK ONE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 2, 1962

Flomaco
Well No. 29 is located 990 ft. from [N] line and 1650 ft. from [E] line of sec. 35


NE/4 Section 35 T-30-N R-8-W NP1M
(of 36 and 36 sec.) (Twp.) (Range) (Section)
Blanco Mesavilla San Juan New Mexico
(Name) (County or Subdivision) (State or Territory)

The elevation of the druck floor above sea level is 5961 ft. G. L.

DETAILS OF WORK

(State nature of and reported depths to objectives under clear logs, weights, and lengths of proposed casings; indicate modifying jobs, cementing points, and all other important proposed work)

Broken head has pressure, propose to perforate 7" casing at 990' break circulation with mud and follow with approx. 400 sacks cement to seal off source of pressure.



I understand that this plan of work must be approved in writing by the Geological Survey before operations may be commenced.

Company Delhi-Taylor Oil Corporation

Address P. O. Box 1122

Farmington, New Mexico

Original signed by
By G. T. HIGGINBOTHAM
G. T. Higginbotham
Title District Superintendent