

|          |  |  |  |
|----------|--|--|--|
| <b>X</b> |  |  |  |
|          |  |  |  |
|          |  |  |  |
|          |  |  |  |

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. SP 078139  
Unit Sandoval Gas Unit B

SUNDRY NOTICES AND REPORTS ON WELLS

|   |   |          |
|---|---|----------|
| NOTICE OF INTENTION TO DRILL.....                   | SUBSEQUENT REPORT OF WATER SHUT-OFF.....        | <b>X</b> |
| NOTICE OF INTENTION TO CHANGE PLANS.....            | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING..... |          |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....     | SUBSEQUENT REPORT OF ALTERING CASING.....       |          |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL..... | SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR..... |          |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....        | SUBSEQUENT REPORT OF ABANDONMENT.....           |          |
| NOTICE OF INTENTION TO PULL OR ALTER CASING.....    | SUPPLEMENTARY WELL HISTORY.....                 |          |
| NOTICE OF INTENTION TO ABANDON WELL.....            |   |          |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Sandoval Gas Unit #3

Farmington, New Mexico June 18, 1959

Well No. 1 is located 890 ft. from N line and 940 ft. from E line of sec. 35

NW/4 Section 35  
(1/4 Sec. and Sec. No.)

T30N  
(Twp.)

R9W  
(Range)

N.H.P.M.  
(Meridian)

Blanco-Pictured Cliffs  
(Field)

San Juan  
(County or Subdivision)


New Mexico  
(State or Territory)

The elevation of the derrick floor above sea level is 5741 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On June 8, 1959, 4-1/2" casing was set at 2537 feet and cemented with 600 sacks cement containing 4% gel and 1-1/4 pounds Tuf Plug per sack followed by 75 sacks neat cement. Circulated out 30 sacks cement. After 48 hours tested casing with 3000 pounds for thirty minutes with no drop in pressure.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Pan American Petroleum Corporation

Address Box 487

Farmington, New Mexico

ORIGINAL SIGNED BY  
By R. M. Bauer, Jr.

Attn: L. O. Spear, Jr.

Title Area Engineer