


(SUBMIT IN TRIPLICATE)

Land Office **New Mexico**

Lease No. **012150**

Unit

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<b>Workover</b>	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 23, 19 61

Federal "FC"

Well No. **1-31** is located **790** ft. from **N** line and **1820** ft. from **W** line of sec. **31**

**NE 1/4 Sec. 31**  
(1/4 Sec. and Sec. No.)

**30N**  
(Twp.)

**11W**  
(Range)

**N.M.P.M.**  
(Meridian)

**Undesignated**  
(Field)

**San Juan**  
(County or Subdivision)

**New Mexico**  
(State or Territory)

The elevation of the derrick floor above sea level is **5822** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

April 4, 1959 - Moved in well service unit and swabbed well down. Will make some gas but too much water. Ran Lane Wells radioactive tracer log. Log showed that all of frac went into the lower part of perforated interval. Well shut in.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **John H. Trigg**  
Address **P. O. Box 520**  
**Roswell, New Mexico**

By *John H. Trigg*  
Title **Owner**