

5-USGC
2-Compass
1-File

X			

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. SP 080466
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			
Intention to Recomplete	X		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 18, 1961

Well No. 1-35 is located 890 ft. from N line and 890 ft. from W line of sec. 35

NW/4 NW/4 Section 35 30N 14W NMFM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Basin-Dakota San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

Ground Level

The elevation of the ~~wellhead~~ above sea level is 5584 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Plan to workover well as follows:

1. Kill well
2. Drill bridge plug which is set at 5883 and clean out to 6000'
3. Perf at 5913'
4. Run packer and SWF under packer with approximately 30,000 gallons water and 20,000# sand.
5. Pull packer, clean out and run 2-3/8" O.D. tubing.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Compass Exploration, Inc.

Address Box 1138
Farmington, New Mexico

Original signed by T. A. Dugan

By _____

Title Engineer