

1954

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. SF 078619
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 2, 1954

E.H. Pipkin No. 1 ²

Well No. _____ is located 700 ft. from XX line and 600 ft. from E line of sec. 31
XX

Section 31, T. 30 N., R. 14 E., N.M.
(Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Wildcat San Juan County New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

In drilling stratigraphic test, gas was encountered in Pictured Cliffs Sandstone, and it is desired to ^{cement} set pipe on top of Pictured Cliffs ^{230' to 250'} and attempt to complete as gas well in Pictured Cliffs Formation.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Lucille H. Pipkin, Independent Operator

Address P.O. Box 1174

Roswell, New Mexico

By Lucille H. Pipkin

Title Operator