SANTA FE FILE U.S.G.S. LAND OFFICE TRANSPORTE	R GAS	3	1-P.A.	.Speez)				COMMISSION	FORM C-103 (Rev 3-55)		
PRORATION O	FFICE		(Sub	mit to appropr	iate Distri	ct Office	as per Co.	mmission Rule 1	1106)		
Name of Con					Addre	ess					
<b>Bota</b> Lease	Deve Lopus	pat Co.		Well No.	Z3	Fotr.	Club Pl	leze, Fermin	gton, New Mexico		
	Paul Palm	82		well No.	Unit Letter	Section 26	1 ownship	1	Range 12 #		
Date Work Performed Poo			ool Flore V	Flore Vista Meseverd			County San Juan				
		·		IS A REPORT		appropria	ite block)	Age Chin			
Beginn	Beginning Drilling Operations			Casing Test and Cement fob			Other (Explain):				
	☐ Plugging			Remedial Work				Pulled thg. & CO			
Witnessed by	**************************************	Manage		Position		į(	Company	RL MAF	75 1964 30 N. COM.		
	Jenn 1	· Manager						leta Developa	nent Co.		
			FILL IN BE	LOW FOR RE	MEDIAL Y		PORTS OF	NLY			
D F Elev. T D			PBTD		Producing Inverval			Completion Date			
Tubing Diameter Tub		ibing Depth	ig Depth Oil Str			ng Diameter Oil String Depth					
Perforated In	terval(s)						<u></u>				
Open Hole Interval						Producing Formation(s)					
				RESULTS	S OF WORL	KOYER					
Test	Date of Test				oduction FPD			GOR Cubic feet/Bbl	Gas Well Potential		
Before Workover							F D	Cubic feet/ Du	MCFPD		
After Workover											
	OIL CONS	ERVATIO	ON COMMISSIO	М	I here to the	e best of m	ny knowledg	ge.	bove is true and complete		
Approved by Original Signed Emery C. Arnold					Name	Name JOHN T. HAMPTON					
Title Supervisor Dist. # 3						Position Manager					
Date MAD 5 1004						Company Sets Development Co.					