

(SUBMIT IN TRIPLICATE)

Indian Agency

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Navajo

Allottee _____

Lease No. **14-20-603-2020**

			X

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	X		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 10, 1961

Well No. 1 is located 1980 ft. from S line and 660 ft. from E line of sec. 30

52/4 Sec. 30
(4 Sec. and Sec. No.)

30N - 17N - NMPM
(Type) (Range)

(Meridian)

Wildcat
(Field)

San Juan

(County or Subdivision)

New Mex100

(State or Territory)


The elevation of the derrick floor above sea level is 4256 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Remove surface pipe.

Fill hole to surface with cement. Place 5ft. marker at surface.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Arizona Explorations, Inc.

Address 417 Meadows Building

Dallas 6, Texas

Bv

Title

V.D.