

(SUBMIT IN TRIPLICATE)

Indian Agency -----

Nava jo

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. **14-20-603-2020**

			x

SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

11-27-61 _____ 19____

Well No. 1 is located 1980 ft. from ~~the~~^S line and 660 ft. from ~~E~~^W line of sec. 30

SE/4 Sec. 30

(1/4 Sec. and Sec. No.)

30N - 17W - NMPM

(Twp.)

(Range)

(Meridian)

Wildcat

(Field)

San Juan

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is 4956 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Removed surface pipe. Filled hole to surface with cement. Placed 5 ft. marker at surface. Cleaned up location.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Arizona Explorations, Inc.

Address 417 Meadows Bldg.

Dallas 6, Texas

By

Title

V.P.

1-5-50-1-1

AVIATION

1-5-50-1-1

1-5-50-1-1

1-5-50-1-1

1-5-50-1-1

1-5-50-1-1

1-5-50-1-1

1-5-50-1-1