



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 9F-078107 2
Unit BYN

Co. Loc. No. PH 65-197-57

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY <u>DST</u> <u>X</u>
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

NORTH W. YEARFLOW UNIT

Farmington, New Mexico January 27, 1958

Well No. 1 is located 1980 ft. from S line and 1980 ft. from W line of sec. 28
NE/4 of SW/4 T-30-N R-15-W
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wilcox San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5219 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

1/21/58: DST No. 3 from 2814' - 2909' w/1" TC & 3/4" BC. TO 23 min. Weak blow and died at end of test. R covered 40' of drilling mud. IM 1250#, min. & max F 25#, Final 1250#. BU after 30 min - 800#. Chloride: Ditch 1650 PPM, Test 2475 PPM. Test satisfactory.

1/25/58: DST No. 4 from 3982' - 4015', 1" TC & 3/4" BC. TO 1 hr. Very weak blow 45 min. & died. Rec 5' drlg. mud. IM 1935, MF 1250, Max F 25, Final 1935#. BU after 30 min. 35#. Test satisfactory.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Humble Oil & Refining Company

Address Box 1268

Farmington, New Mexico

By Russell M. Lilly
Russell M. Lilly
Dist. Supt.

Title