

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe

Lease No. 11-6474

Unit Hall

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 8, 1959

Well No. 1 is located 1980 ft. from N line and 660 ft. from E line of sec. 27

NW/4-27 (Sec. and Sec. No.) 30N (Twp.) 15W (Range) NMPM (Meridian)


Wildcat (Tocito) (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 5207 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

- 7-3-59 Spudded 12 1/4" hole 9:00 PM.
4 At TD of 180' set 8 5/8" 24# J-55 ST&C casing at 176' & cemented to the surface w/130 sx reg cement. Plug down 7:00 AM.
5 WOC
6 WOC 48 & tested w/1000 psi for 30 min, held ok.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations are commenced.

Company Monsanto Chemical Co.

Address Drawer 1829

Midland, Texas

By A. W. White

Title Reg. Prod. Supt.