

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. NM 912708
Unit E/2 of Sec. 30

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

RECEIVED
SEP 6 1956
GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO


Ben R. Howell
Well No. 3 is located 1475 ft. from [N] line and 1090 ft. from [E] line of sec. 30
NE 1/4 of Sec. 30
(1/4 Sec. and Sec. No.) 30N 8W NMPM
(Twp.) (Range) (Meridian)
Blanco (Mesaverde)
(Field) San Juan New Mexico
(County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5808 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Ran 67 joints (2640') of 7 5/8 26.40# J-55 SS Casing, landed at 2650' Cemented with 250 sacks. Casing was pressured to 500# for 1 hour with no drop in pressure. After cement set, plug was drilled and hole blown dry with gas. It remained dry and drilling ahead with gas was resumed.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Delhi-Taylor Oil Corporation

Address P. O. Box 1175

Farmington, New Mexico

By [Signature]

Title Dist. Supt.

200 1/2

1230

CCCI

1965

000



30. - 2 -

$\frac{1}{\sqrt{2}}$