

Southern Union Gas Company

P. O. Box 757
FARMINGTON, NEW MEXICO

November 14, 1957

Locke Taylor Drilling Company
407 N. Allen
Farmington, New Mexico

Dear Sir:

This letter is to inform you of the condition and status of your well producing into our system. We hope that this information will prove useful to you in the event you deem it necessary to take any action.

Well Production Status **Marginal**

Well Name	Location	Pool Unit
Smith #1	SW(L) 27 30 12	Fulcher Kutz Pictured Cliff

- ☐ Well is extremely wet.
- ☐ Shale, sand, and drilling mud are emitted when cleaning well.
- ☐ Well will not clean any fluid when blown.
- ☐ Cleaning does not increase well's ability to produce.
- ☐ Syphon line is ineffective.
- ☒ Casing is leaking.
- ☐ Tubing is plugged.
- ☐ Well indicates a bridge between tubing and casing.
- ☐ Well will not produce. Possibly it is logged off or bridged over tubing.
- ☐ Well head valves are working improperly.
- ☐ Well is shut in by New Mexico Oil Conservation Commission orders.
- ☒ Other: Well will not produce into our gathering system at very low pressure.

Recommendations:

- ☐ Well should be reworked.
- ☐ Well should have an intermitter installed to clean it daily for maximum production.
- ☐ Other: _____

Sincerely yours,

SOUTHERN UNION GAS COMPANY

Rudy Motto
Rudy Motto
Dispatchers' Superintendent



cc: New Mexico Oil Conservation Commission