

(SUBMIT IN TRIPLICATE)

Indian Agency 14-20-603-2020

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 5, 1959

Well No. 1 is located 2310 ft. from N line and 990 ft. from E line of sec. 29

SW NW 30 17 NM PM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
WILDCAT SAN JUAN NEW MEXICO
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 4976 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well was plugged with 150 feet of cement in bottom. Cement 500 to 440 feet 3 sx. from 60 to 50 feet 2 sx. in top of surface csg. a dry hole marked installed and well abandoned on May 1, 1959.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company KING OIL COMPANY
Address 745 PETROLEUM CLUB BUILDING
DENVER 2, COLORADO

Bernard King
By _____

Title PRESIDENT

