



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office San Juan Co., N.M.
Lease No. 67-07010
Unit Sec. 25, T-38N, R-11W, N.M.T.M., San Juan Co., N.M.

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

Setting Surface Casing
Setting 5 1/2" Casing

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 2, 1957

Well No. 1st is located 25 ft. from N line and 30 ft. from E line of sec. 25
NE 1/4 Sec. 25
Antec. Richard Cliffe San Juan County New Mexico

The elevation of the derrick floor above sea level is 6150 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

1. Cemented 127' of 9 5/8" casing with 125 sacks cement and 2% calcium chloride on September 4, 1957. Drilled plug and tested with 5000' pressure - no leaks on September 5, 1957. 32.30' 11-40 Casing
2. Cemented 265' of 8 1/2" casing with 100 sacks cement and 2% gel on September 10, 1957. 15.30' 11-35 Casing

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Southern Union Gas Company
Address 1114 East Mainline
Tulsa 1, Texas
Attn: A. M. Wiederkehr

By Paul J. Clate
Title Drilling Super