

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency

Window Rock

Allettee

Lease No. **14-20-603-1045**

SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	NOV 29 1961
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	U.S. GEOLOGICAL SURVEY
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	FARMINGTON, NEW MEXICO
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 23, 1961

Navajo

Well No. **6** is located **1650** ft. from **N** line and **1650** ft. from **E** line of sec. **27**

NW/4 **27**
(1/4 Sec. and Sec. No.)

30N
(Twp.)

19W
(Range)

NMPM
(Meridian)

Wildcat
(Field)

San Juan County
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is **5000** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total depth 150'. Filled hole from surface to total depth with cement.

Erected dry-hole marker. Cleaned location, installed dry hole marker.

Hole abandoned.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **HARRELL BUDD**

Address **1813 CAMINO RIO**

FARMINGTON, NEW MEXICO

By **HARRELL BUDD**

Title **Consulting Geologist**