

(SUBMIT IN TRIPLICATE)

Indian Agency _____

Window Rock

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allettee _____

Lease No. **14-20-603-1045**

SUNDRY NOTICES AND REPORTS ON WELLS

NOV 29 1961

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____	U. S. GEOLOGICAL SURVEY FARMINGTON, NEW MEXICO <input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____	
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____	
NOTICE OF INTENTION TO ABANDON WELL _____		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 22, 19 **61**


Navajo
Well No. **2** is located **1650** ft. from **[N]** line and **990** ft. from **[E]** line of sec. **37**
NE/4 **27** **T30N R19W** **NM PM**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat **San Juan County** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **505** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled 4-1/4" hole from surface to 250'. Encountered slight show of oil at 90'. Filled hole with cement from surface to total depth. Erected dry hole marker. Cleaned location and abandoned.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **HARRELL BUDD**
Address **1613 CAMINO RIO**
FARMINGTON, NEW MEXICO
By **HARRELL BUDD**
Title **Consulting Geologist**