


(SUBMIT IN TRIPLICATE)

Land Office Santa FeLease No. 078213

Unit _____



30 N

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	XX
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 25, 1960

Well No. 2-26 is located 1140 ft. from N line and 990 ft. from E line of sec. 26NE NE Section 26 30 North 13 est NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)Wildcat San Juan County New Mexico
(Field) (County or Subdivision) (State or Territory)The elevation of the derrick floor above sea level is _____ ft. 5792 G. L.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Operator set 6583' of 4-1/2", 9.5# & 11.6#, ran centralizers and scratchers through interval 6350-6500'. Circulated and reciprocated for one hour prior to cementing.

Cemented w/280 sx 1:1 Diamix w/2% gel. Used top and bottom rubber plugs. Displaced top plug with 106 BW and bumped same with 2000 psi pressure.

Struck up

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company COMPASS EXPLORATION, INC.Address 1645 Court PlaceDenver, Colorado

By

P. J. FARRELLY

Title

Geologist