

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL
	GAS
PRODUCTION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Pan American Petroleum Corporation		Address Box 480, Farmington, New Mexico	
Lease McCoy Gas Unit "C"	Well No. 1	Unit Letter A	Section 28
Township T-30-N		Range R-12-W	
Date Work Performed	Pool Flora Vista Mesaverde	County San Juan	

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☒ Other (Explain): **Frac**
- ☐ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Perforated the Cliffhouse section of the above well with 4 shots per foot 3277'-3286'.
 Flowed well to clean up. Preliminary potential test 5356-MCFPD.
 Completed 4-13-62 as shut-in Flora Vista Mesaverde Field Well.

Witnessed by	Position	Company
--------------	----------	---------

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA				
D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION		I hereby certify that the information given above is true and complete to the best of my knowledge.	
Approved by Original Signed By A. R. KENDRICK		Name Original signed by R. M. BAUER, JR	
Title PETROLEUM ENGINEER DIST. NO. 3		Position Senior Petroleum Engineer	
Date APR 20 1962		Company Pan American Petroleum Corporation	