

(SUBMIT IN TRIPLICATE)

Indian Agency Navajo

Window Rock

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. 14-20-603-1045

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 13, 19 62

Well No. 1 is located 330 ft. from N line and 2310 ft. from E line of sec. 27

NE/4 27
(1/4 Sec. and Sec. No.)

30N
(Twp.)

19W
(Range)

N40°N
(Meridian)

Window
(Field)

San Juan County
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 4982 ft.


DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled 6 1/4" hole to 150'. Set 2" tubing at 90'. Rigged up windmill to test oil show. Oil production too small to be commercial. Pulled tubing. Rig down windmill. Set cement plug from 0 to 150'. Erected dry hole marker. Hole abandoned September 10, 1962.

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

SEP 17 1962



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Harrell Budd

Address 1413 Camino Rio

Farmington, New Mexico

By Harrell Budd

Title Consulting Geologist