

(SUBMIT IN TRIPLICATE)  
UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.  
Approval expires 12-31-60.

Land Office Santa Fe  
Lease No. 070194  
Unit Lease 100

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	A
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 1, 1950


Well No. 12 is located 500 ft. from N line and 1500 ft. from E line of sec. 1  
304 (1/4 Sec. and Sec. No.) 10W (Twp.) 22N (Range) 100 (Meridian)  
Blanco (Field) New Mexico (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 5225 ft.

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

3-21-50, Total Depth 5605'.  
 Run 23 joints 5 1/2", 15.0#, J-55 liner (1735') set at 4455' to 5605' with  
 60 lb. regular cement, 60 lb. cement, 25 Gal. 12% Fluoride.  
 Hold 1000' for 30 minutes.  
 Top of cement by temperature curve, at 4455'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 991  
Parliament, New Mexico

By [Signature]

Title Petroleum Engineer