STATE OF NEW MEXICO
OIL CONSERVATION COMMISSION
DISTRICT NO. 3
Phone 99 P. O. Box 697
AZTEC, NEW MEXICO

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Santa Fe
Land Office
078194
Lease No.
Unit

RECEIVED
OCT 25 1951
OIL CONSERVATION COM
DIST. 3

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 22, 19 51

Ludwick
Well No. 2 is located 1040 ft. from {N/S} line and 1090 ft. from {E/W} line of sec. 19

S. E. 1/4 of Sec. 19 (¼ Sec. and Sec. No.) T-30-N (Twp.) R-10-W (Range) NMPM (Meridian)

Wildcat (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6220 ft. D. F. (Alti)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Prior to drilling plug casing was pressured to 1200# for 1 hour with no drop, after drilling plug rams were closed on Blowout Preventer and pressured to 1200# with no drop. Cable Tools drilled to T. D. of 2795' and well was shot with 350 qts S. N. G. from 2759' to 2795'. Ran 129 jts of 1" Siphon line landed at 2709'. Well is now shut in for test.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Delhi Oil Corporation

Address P. O. Box 1175
Farmington, N. Mex.

By J. B. Howell
Title Superintendent

Land Office .....

Lease No. .....

Unit .....

(SUBSEQUENT REPORT)

UNITED STATES

DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

OIL CONSERVATION COMMISSION

SUNDRY NOTICES AND REPORTS ON WELLS

SUBSEQUENT REPORT OF WATER SHUT-OFF	[illegible]
SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	[illegible]
SUBSEQUENT REPORT OF ALTERING CASING	[illegible]
[illegible]	[illegible]
SUBSEQUENT REPORT OF ABANDONMENT	[illegible]
[illegible]	[illegible]
[illegible]	[illegible]

(Indicate above by check mark nature of report, notice, or other data)

[illegible]

[illegible] well is located [illegible] ft. from [illegible] line and [illegible] ft. from [illegible] line of sec. [illegible]

(Lease or Serial No.) (Township) (Range) (Meridian)

(Field or Pool name) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is [illegible] ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

[illegible]

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company [illegible]

Address [illegible]

[illegible]

[illegible]