


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 000113
Unit Schram



SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED

APR 9 1958

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		
	Water Frac.	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 7, 1958

Well No. 1 is located 100 ft. from S line and 100 ft. from E line of sec. 23


SE Sec. 23 30N 11W T.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Astec, P.C. San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6057 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

4-4-58. Total Depth 2506'. Plug back T.D. 2574'. Water fractured Pictured Cliffs perforated intervals 2486-2534' with 37,600 gallons water and 35,000# sand. 1900# max. pr. 2300, avg. tr. w. 1700, 1900, 1900, 1650, 2300#. I.R. 50 BPM. Flush 2300 gallons.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 977
Farmington, New Mexico

By Original Signed D. C. Johnston

Title Petroleum Engineer