TABULATION OF DEVIATION TESTS Danburg Gas Unit B #1 B Bad Com # / PAN AMERICAN PETROLEUM CORPORATION

<u>DEPTH</u>	DEVIATION
505'	3/4°
906	1/2
1245	1
1501	3/4
1908	3/4
2503	3/4
3048	3/4
3401	1/2
3695	1/4
4071	1/4
4416	1
4817	1/2
5263	1
5763	1/2
6090	1



AFFIDAVIT

THIS IS TO CERTIFY that to the best of my knowledge the above tabulation details the deviation test taken on PAN AMERICAN PETROLEUM CORPORATION'S Danburg Gas Unit B No. 1, located 1935 FSL and 940 FEL Section 21, T-30-N, R-12-W, San Juan County, New Mexico.

Signed R. H. Beers
Title Administrative Assistant
THE STATE OF COLORADO)

COUNTY OF DENVER)

BEFORE ME, the undersigned authority, on this day personally appeared R. H. Beers known to me to be Administrative Assistant for Pan American Petroleum Corporation and to be the person whose name is subscribed to the above statement, who, being by me duly sworn on oath, states that he has knowledge of the facts stated herein and that said statement is true and correct.

SUBSCRIBED AND SWORN TO before me, a Notary Public in and for said County and State this 26 day of August, 1965.

Catherine L Eckerman Notary Public

My Commission Expires 3-12-67

