



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office San Juan
Lease No. 981001
Unit 1/2 Sec. 23

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 26, 1957

Well No. 7 is located 970 ft. from N line and 1400 ft. from E line of sec. 23

1/4 Sec. 23 (1/4 Sec. and Sec. No.) 34N (Twp.) 2W (Range) 107E (Meridian)
Blanco - Rosoverde (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 4001 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We propose to GO to TD 5095, deepen to approx. 5150'. Set & cement 5" liner 4300 to 5150, perforate P.L. & C.L. 2 stage ~~water/sand free~~ Water/sand free for re-completion in Rosoverde.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Bulhi-Taylor Oil Corporation

Address P. O. Box 1175
Farmington, New Mexico

By M. H. Hume
Title Dist. Supt.

