

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved
Budget Bureau No. 41 R1424.
5. LEASE DESIGNATION AND SERIAL NO.

SF078125-B

6. INDIAN ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
(Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR El Paso Natural Gas Company		8. FARM OR LEASE NAME Pierce A
3. ADDRESS OF OPERATOR P. O. Box 990, Farmington, NM 87401		9. WELL NO. 1A
4. LOCATION OF WELL (Report location clearly and in accordance with any state requirements.* See also space 17 below.) At surface 800'S, 1670'E		10. FIELD AND POOL, OR TUBECUT Blanco Mesa Verde
14. PERMIT NO.		11. SEC., T., R., AND OR E., AND SURVEY OR AREA Sec. 15, T-50-N, R-10-W N.M.P.M.
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6374' GL		12. COUNTY OR PARISH AND STATE San Juan New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETION ☐
ABANDON* ☐
CHANGE PLANS ☐

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☒
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐


(NOTE: Report results of multiple completion on Well Completion or Recombination Report and Log Form)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

06-22-76 Killed well and pulled 2 3/8" tubing. Set BP at 4890'. Pressure tested to 3500 psi--OK.

06-23-76 Perf'd Cliff House 4665', 4674', 4682', 4708', 4736', 4794', 4831', 4844', 4858' with 1 shot per zone. Frac'd with 45,000#--20/40 sand and 50,000 gallons water. No sets of balls dropped. Flushed with 6600 gallons water. Drilled BP at 4890'. Cleaned out to BP at 5235' and drilled BP.

06-25-76 Reran 2 3/8" tubing, 5615' set at 5627'.



RECEIVED

JUL 9 1976

U. S. GEOLOGICAL SURVEY

18. I hereby certify that the foregoing is true and correct

SIGNED M. J. Dumas

TITLE Drilling Clerk

DATE July 9, 1976

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____