

NEW MEXICO OIL CONSERVATION COMMISSION
NORTHWEST NEW MEXICO PACKER-LEAKAGE TEST

Operator EL PASO NATURAL GAS COMPANY				Well Name and Number Sunray A #1			
Location of Well Unit A Sec. 15 Twp. 30 Rge. 10				TYPE OF TEST →	Annual - (Give Year) 1974	Initial - (Give Date)	☐ NEW ☐ OWWO ☒ CASING ☒ TUBING
UPPER COMPLETION	Reservoir or Pool PC	☒ GAS ☐ OIL	☒ FLOWING ☐ ARTIFICIAL LIFT	Production String			
LOWER COMPLETION	Reservoir or Pool MV	☒ GAS ☐ OIL	☒ FLOWING ☐ ARTIFICIAL LIFT	Production String			

Date	Upper Zone		Lower Zone		
	Shut-in		Shut-in	Flow Test	
	Casing	Tubing	Tubing	Tubing	Flow Rate
3-11	271	271	327	X	X
3-12	287	287	337		
3-13	297	297	344		
3-14	310	310	X	240	91 MCF/D
3-15	321	321		215	74 MCF/D

Remarks:



The results of this test indicate (No Packer Leakage) (Packer Leakage) in this well.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

APPROVED 3-18-74
NEW MEXICO OIL CONSERVATION COMMISSION
BY AR Deudeich
PETROLEUM ENGINEER DIST. NO. 3

OPERATOR EL PASO NATURAL GAS COMPANY
BY Loren W. Fothergill
TITLE Well Test Engineer
DATE 3-18-74

DAYS

1 2 3 4 5

PRESSURE
 Paig
 700
 Both Zones
 Shut In
 Flowing
 MV.

E P N G
 Annual Packer Leakage Test
 1974

SUNRAY A #1 (PM)
 Unit A Sec. 15-30-10
 San Juan Co., New Mexico

o PC Zone • MV Zone

