



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **019410**
Lease No. _____
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	X
NOTICE OF INTENTION TO ABANDON WELL	Surface Casing Details	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 7, 19**55**

Pudco Brington Federal
Well No. **1** is located **1114** ft. from **1114** line and **945** ft. from **945** line of sec. **15**
SW 1/4 Sec. 15
30 North 11 West **N.M.P.M.**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Artes Pictured Cliff **San Juan** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **5818** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 12-4-55

Ran 3 Jts. @ 5/8" OD new mals 8 rd thd 32.80# N-40 R-2 STAC casing (95').
Landed 10' below K.B. @ 106'.

Cemented with 100 sax bulk reg. cement. Displaced with 6 bbls water. WOC 12:20 A.M.
12-5-55. Circulation good, pipe free. Approx. 20 sax cement returns.

Tested casing to 1000# for 30 minutes. Test OK.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **PUDCO DEVELOPMENT, INC.**

Address **107 West Chase**

Artes, New Mexico

By **H. E. Maxwell, Jr.**
Title **Supt. Prod. Dept.**