

Dennis E. Frost
P.O. Box 1980, Hobbs, NM
DEPUTY OIL & GAS INSPECTOR
P.O. Drawer DD, Artesia, NM 88211
APR 10 1998
1000 Rio Brazos Rd, Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

SUBMIT 1 COPY TO
APPROPRIATE
DISTRICT OFFICE
AND 1 COPY TO
SANTA FE OFFICE

Approved **PIT REMEDIATION AND CLOSURE REPORT**

Operator: RODDY PROD. CO. Telephone: 325-5750
Address: P.O. Box 2221, FARMINGTON, NM 87499
Facility or: PRICE No. 1
Well Name API: 30-045-09477
Location: Unit or Qtr/Qtr Sec K Sec 17 T 30N R 11W County SAN JUAN
Pit Type: Separator Dehydrator Other BLOW
Land Type: BLM , State , Fee X, Other

Pit Location: Pit dimensions: length 10, width 10, depth 2
(Attach diagram) Reference: wellhead X, other
Footage from reference: 3'
Direction from reference: N Degrees 0° East North
of West South

Depth To Ground Water:
(Vertical distance from
contaminants to seasonal
high water elevation of
ground water)

Less than 50 feet (20 points)
50 feet to 99 feet (10 points)
Greater than 100 feet (0 Points) 20

Wellhead Protection Area:
(Less than 200 feet from a private
domestic water source, or; less than
1000 feet from all other water sources)

Yes (20 points)
No (0 points) 0

Distance To Surface Water:
(Horizontal distance to perennial
lakes, ponds, rivers, streams, creeks,
irrigation canals and ditches)

Less than 200 feet (20 points)
200 feet to 1000 feet (10 points)
Greater than 1000 feet (0 points) 0

RANKING SCORE (TOTAL POINTS): 20

Date Remediation Started: 11-24-97 Date Completed: 11-24-97

Remediation Method: Excavation Approx. cubic yards 0
(Check all appropriate sections) Landfarmed Insitu Bioremediation

Other PIT TESTED PRIOR TO POSSIBLE REMEDIAL
EFFORTS - NO EXCAVATION REQUIRED

Remediation Location: Onsite offsite NO REMEDIATION
(ie. landfarmed onsite,
name and location of
offsite facility)

General Description of Remedial Action: NONE - NO CONTAMINATES
DETECTED.

Ground Water Encountered: No X Yes Depth

Final Pit:
Closure Sampling:
(if multiple samples,
attach sample results
and diagram of sample
locations and depths)

Sample location see Attached Documents

Sample depth 4' BELOW PIT BOTTOM

Sample date 11-24-97 Sample time 0830

Sample Results

Benzene(ppm) NA

Total BTEX(ppm) NA

Field headspace(ppm) 3.2

TPH 32

Ground Water Sample: Yes No X (If yes, attach sample results)

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST
OF MY KNOWLEDGE AND BELIEF

DATE 11-26-97

SIGNATURE J. C. Blagg PRINTED NAME AND TITLE J.C. Blagg - P.E. #11607

BLAGG ENGINEERING, INC.

P.O. Box 87, Bloomfield, New Mexico 87413

Phone: (505)632-1199 Fax: (505)632-3903

**FIELD MODIFIED EPA METHOD 418.1
TOTAL PETROLEUM HYDROCARBONS**

Client: Roddy Prod. Co.
Sample ID: Blow Pit C @ 4'
Project Location: Price No. 1
Laboratory Number: TPH #1944

Project #:
Date Analyzed: 11-24-97
Date Reported: 11-24-97
Sample Matrix: Soil

Parameter -----	Result, mg/kg -----	Detection Limit, mg/kg -----
Total Recoverable Petroleum Hydrocarbons	32	20

ND = Not Detectable at stated detection limits.

QA/QC:	QA/QC Sample TPH mg/kg -----	Duplicate TPH mg/kg -----	% *Diff. -----
	608	568	7

*Administrative Acceptance limits set at 30%.

Method: Modified Method 418.1, Petroleum Hydrocarbons, Total
Recoverable, Chemical Analysis of Water and Waste,
USEPA Storet No.4551, 1978

Comments: Blow Pit - Roddy Prod. Co. - Price No. 1

J. C. Blagg
Analyst

Hehon Vef
Review