

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 07774
Unit Schumanher

SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 2, 1961

Well No. 11 is located 1650 ft. from 100 line and 1650 ft. from 10 line of sec. 18


S.M. Sec. 18 (1/4 Sec. and Sec. No.) 30-E (Twp.) 10-W (Range) N.M.P.M. (Meridian)
Basin Dakota (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 5222 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This Plat is re-issued to show corrected elevation.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company
Address Box 990
Farrington, New Mexico
By _____
Title Petroleum Engineer

Well Location and Acreage Dedication Plat

Section A.

Date **FEBRUARY 14, 1961**

Operator **EL PASO NATURAL GAS COMPANY** Lessee **SCHUMACHER** SF **077764**
 Well No. **11** Unit Letter **K** Section **18** Township **30-N** Range **10-W** NE 1/4
 Located **1650** Feet From **SOUTH** Line. **1650** E. of P. 1/4 **WEST** 1/4
 County **SAN JUAN** G. L. Elevation **6272** Estimated Acreage **316.50**
 Name of Producing Formation **DAKOTA** Pool **BASIN DAKOTA**

1. Is the Operator the only owner in the lot, state acreage owned on the plat above?
 Yes ☐ No ☐
2. If the answer to question one is "No", have the interest of all the owners been ascertained by a written agreement or otherwise? Yes ☐ No ☐ If answer is "yes", Type of Co-ordination:

3. If the answer to question two is "No", list all the owners and their respective interests below:
 Owner _____ Land Description _____

Section B.


Note: All distances must be from corner boundaries of lot.

This is to certify that the information in Section A above is true and complete to the best of my knowledge and belief.
 (Signature) _____

(Operator)
ORIGINAL SIGNED J.J. TILLERSON

(Signature) _____ Representative

(Signature) _____ (Address) _____



NOTE: THIS PLAT IS RE-ISSUED TO SHOW CORRECTED ELEVATION. 2 28 61

This is to certify that the above plat was examined from the records of the Commission, made by me or under my supervision and that the same are true and correct to the best of my knowledge and belief.

(Seal)

Date Surveyed

MAY 12, 1963

Paul O. Kilmer
 (Signature of Paul O. Kilmer)