



Key Energy Services. Inc.
Four Corners Division

PLEASE REMIT TO:
P.O. BOX 676364
DALLAS, TX 75267-6364

(505) 327-4935

I N V O I C E

STATE OF NEW MEXICO OCD
1000 RIO BRAZOS RD
AZTEC NM 87410

PAGE 1
INVOICE NO. 160104872
INVOICE DATE 05/29/02
ACCOUNT NO. 17420
JOB NUMBER 25818
OPERATOR LUPE MONTOYA
ORDERED BY CHARLIE PERRIN
CONTRACT # 10-521-07-07369
AFE/BA#

WELL: FANNIE WARD #1
LOCATION: NM San Juan

UNIT: 490

03/15/02 TO 03/22/02

Additional Rig Hrs. due to an abundance
of Mud circulated out of hole and
faulty Master Valve.

3/15/02 25818

1.00	Bid Price To Plug & Abandon Well	29004.90	29,004.90
9.50 HR	Rig Hours	210.00	1,995.00
40.00 SAC	Cement	10.00	400.00
2.00 HR	Crew Travel	100.00	200.00
2.00 DAY	Crew Pickup	100.00	200.00
1.00 JOB	Supervisor	350.00	350.00
1.00 EA	ENVIRO-TECH	750.00	750.00
1.00 JOB	Waste Haul	995.00	995.00
1.00 JOB	Waste Disposal	540.00	540.00
1.00 JOB	Repair Culvert	688.77	688.77
1.00 DAY	Cement For Anchors	634.00	634.00
1.00-EA	Adjustment - Earth Pit	1150.00	1,150.00-
1.00 EA	10% Handling Charge on ENVIROTECH -TECH	207.28	207.28
	Culvert Repair & Cement for Anchors		
	Work Ticket Subtotal		34,844.95 34,814.95
	Non-Taxable Subtotal		33,780.95
	Taxable Subtotal		1,064.00 1034.00
	NM Sales Tax	5.7500	61.18 59.46
	Invoice Total		34,906.13 \$ 34,874.4



PK
FOR PAYMENT
Charlie Perrin

THANK YOU

INTEREST CHARGED AT THE RATE OF 2.0% PER MONTH OR 24% ANNUM ON ACCOUNTS NOT PAID WITHIN 30 DAYS.
ALL COSTS AND REASONABLE ATTORNEY FEES FOR COLLECTION WILL BE PAID BY THE PURCHASER.



Key Energy Services

FOUR CORNERS
P.O. BOX 900
FARMINGTON, NM 87499

10-521-07-07369
114953

RIG NO. 8

DATE: 3-15-02

COMPANY State of New Mexico
LEASE Fanny Wood
WELL NUMBER # 1
STATE / COUNTY N.M.
SEC. 18 T/S 30N RANGE 11W
LOG. 36-48-62N LAT. 48-02-12W

FROM	TO	<input type="checkbox"/> WORKOVER 1322	<input type="checkbox"/> COMPLETION 6235	WELL CODE	CODE	
7:00	8:30					
		MOVE RIG FRAME YARD TO LOC				M
8:30	9:00	HAVE A SAFETY MEETING				
9:00	9:30	RIG UP				
9:30	2:00	WHILE TAKE WELL HEAD OF IT PRESSURED UP AND				
2:00	4:00	WE GET IT UNDER CONTROL				
4:00	6:00	PUMP WATER AND CLEAN UP AND PUT UP TOWELS				
6:00	6:30	TRAVEL TO YARD				

BA/NO.	CODE	COST	CODE	SALES ITEMS	QTY	PRICE EA.	COST	DOWN HOLE EQUIP.
152405	Pickup # Phone #		142325	S. Stripping Rubber				SIZE COUNT
121945	Rec. Stripping Head		142325	R. Stripping Rubber				TGB
121865	Companion Flange		142305	27/8 Swab Cups				Rods
121820	3000 BOP		142305	2.00 Swab Cups				Rods
121825	5000 BOP		142305	Other Swab Cups				Rods
132215	Power Rod or Tubing Tongs		142310	Oil Saver Rubbers				Rods
121705	2.5 Power Swivel Use Standby		142326	B.J. Tongs Dies				Subs
121710	3.5 Swivel		142326	Peckomatic Tong Dies				Polish Rod
121605	Pump Used Standby		142326	Slip Segments			331316	Fuel Surcharge \$
121910	Pit		162506	Pipe Dope				
121970	Pipe Racks		142315	Wiper Rubbers				
132210	Tong Heads Size							
132260	Slips 1 1/4 1 1/2 2 1/16 3 1/2 4 1/2							
132005	LYT Elevators			RIG TIME Hours		Rate \$		\$
132005	3 1/2 or 4 1/2 Elev.			RIG TIME Hours	11	Rate \$		\$
121850	BOP Rams - Additional		111585	TRAVEL TIME Hours	10	Rate \$		\$
132245	Rod Fishing Tools		111575	FLOW TIME				Accident Y N
132246	Paraffin Knife			EMPLOYEE TIME	Hours	S.S. NO.		
132125	Light Plant		Oper.	Lupe Montoya	11 1/2	585-446671		
121905	T.I.W. Valve		DK. Man	Ruddy Archuleta	11 1/2	521-98-1860		
121845	Closing Unit		F.H.	Cesar Cruz	11 1/2	510-74-1165		
132130	H2S Equipment		F.H.	Trinidad Garcia	11 1/2	457-99-7573		
132110	Rig Ramp		F.H.					
111550	Subsistence							
132255	Standing Valve							
132115	Phone							
162535	Restroom							
132220	Depthometer							
331315	Environmental Waste Surcharge							
111510	Supervisor							
							TOTAL DAILY COST	\$
				Operators Signature	<i>Lupe Montoya</i>			
				Pusher Signature	<i>JH</i>			
				Accepted By				
				A.F.E. No.				
							TOTAL MAN HOURS	46

TRIP OUT	TRIP OUT	TOTAL MAN HOURS	46
TRIP IN	TRIP IN	TRIP IN	
TRIP OUT	TRIP OUT	TRIP OUT	
TUBING SIZE	ROD SIZES	TOTAL FOOTAGE	
SAFETY & ENVIRONMENTAL TOPIC			
COMMENTS: <i>Person Conducting Meeting Lupe Montoya</i> <i>Read Employee Handbook page 30 para 31. No key equipment (lead acids, masts, booms, ladder, etc) will be operated within 10' of overhead powerlines</i>			
NEAR MISSES:			
POTENTIAL HAZARDS:			
ODOMETER READING:	<u>106517</u>	PROPANE:	
ROUND TRIP MILEAGE:	<u>25</u>	RIG HIGHWAY MILEAGE:	
WEATHER:	<u>good</u>	ROAD CONDITIONS:	<u>good</u>
DAILY SAFETY CHECK LIST		WALK AROUND PICKUP INSPECTION	
Safety Glasses <input checked="" type="checkbox"/>	Personal Protective Equip <input checked="" type="checkbox"/>	Tires <u>OK</u>	Check H2S Monitor <input checked="" type="checkbox"/>
Hard Hat <input checked="" type="checkbox"/>	No Loose Fitting Clothes <input checked="" type="checkbox"/>	Lights <u>OK</u>	Check plug in <input checked="" type="checkbox"/>
Steel Toe Shoe <input checked="" type="checkbox"/>	No Sleeveless Shirts <input checked="" type="checkbox"/>	Windshield <u>OK</u>	Make sure it is working <input checked="" type="checkbox"/>
		Oil <u>OK</u>	Pull test tube <input checked="" type="checkbox"/>
			Drill Test <input checked="" type="checkbox"/>
			Rig Inspection <input checked="" type="checkbox"/>



Key Energy Services

FOUR CORNERS
P.O. BOX 900
FARMINGTON, NM 87499 RIG NO. 8

114958

DATE: 3-18-02

CONTRACT STATE of NEW MEXICO
LEASE FANNY WORD
WELL NUMBER #1
STATE / COUNTY N.M.
SEC. 18 T/S 30N RANGE 11W
LOG. 36°-48-62 N LAT. 108°-02-12 W

FROM	TO	<input type="checkbox"/> WORKOVER 1322	<input type="checkbox"/> COMPLETION 6235	WELL CODE	CODE	
6:00	7:00					
		TRAVEL CIVE TO LOC				
7:00	7:30					
		HAVE A Safety meeting				
7:30	8:00					
		PERASHER Tubing Suching Caseing & CASEING 50				
8:00	8:30					
		REMOVE WELL HEAD AND RIG UP B.O.P.				
8:30	10:00					
		REMOVE Stud From WELL HEAD set screws				
10:00	10:30					
		RIG UP FLORE				
10:30	2:00					
		T.O.H. with Tubing 208 Joint				
2:00	3:00					
		T.L.H. with 20 stand Kill string				
3:00	3:30					
		TRAVEL CIVE TO YARD				

BA/NO.	CODE	COST	CODE	SALES ITEMS	QTY.	PRICE EA.	COST	DOWN HOLE EQUIP.		
								SIZE	COUNT	
152405	Pickup # Phone #		142325	S. Stripping Rubber						
121945	Rec. Stripping Head		142325	R. Stripping Rubber				TGB		
121865	Companion Flange		142305	27/8 Swab Cups				Rods		
121820	3000 BOP		142305	2.00 Swab Cups				Rods		
121825	5000 BOP		142305	Other Swab Cups				Rods		
132215	Power Rod or Tubing Tongs		142310	Oil Saver Rubbers				Rods		
121705	2.5 Power Swivel Use Standby		142326	B.J. Tongs Dies				Subs		
121710	3.5 Swivel		142326	Peckomatic Tong Dies				Polish Rod		
121605	Pump Used Standby		142326	Slip Segments			331316	Fuel Surcharge \$		
121910	Pit		162506	Pipe Dope						
121970	Pipe Racks		142315	Wiper Rubbers						
132210	Tong Heads Size									
132260	Slips 1 1/4 1 1/2 2 1/16 3 1/2 4 1/2									
132005	LYT Elevators									
132005	3 1/2 or 4 1/2 Elev.									
121850	BOP Rams - Additional		111585	TRAVEL TIME Hours		Rate \$				
132245	Rod Fishing Tools		111575	FLOW TIME		Rate \$				
132246	Paraffin Knife									
132125	Light Plant									
121905	T.I.W. Valve									
121845	Closing Unit									
132130	H2S Equipment									
132110	Rig Ramp									
111550	Subsistence									
132255	Standing Valve									
132115	Phone									
162535	Restroom									
132220	Depthometer									
331315	Environmental Waste Surcharge									
111510	Supervisor									
							TOTAL DAILY COST	\$		
				Operators Signature	<u>Jupe Montoya</u>					
				Pusher Signature	<u>JH</u>					
				Accepted By						
				A.F.E. No.						

TRIP OUT	TRIP IN	TOTAL MAN HOURS
TRIP IN	TRIP OUT	TRIP IN
TRIP OUT	TRIP IN	TRIP OUT
TUBING SIZE	ROD SIZES	TOTAL FOOTAGE

SAFETY & ENVIRONMENTAL TOPIC
 COMMENTS: Person Conducting Meeting
Read Employee Safety Handbook page 29 and 30 The roof must
be electrically bonded to the shell

POTENTIAL HAZARDS:

ODOMETER READING: 166584
 ROUND TRIP MILEAGE: 55
 WEATHER: good
 PROPANE: _____
 RIG HIGHWAY MILEAGE: _____
 ROAD CONDITIONS: good

DAILY SAFETY CHECK LIST		WALK AROUND PICKUP INSPECTION		B.O.P.	
Safety Glasses <input checked="" type="checkbox"/>	Personal Protective Equip <input checked="" type="checkbox"/>	Tires <u>OK</u>	Check H2S Monitor <input checked="" type="checkbox"/>	Drill <input checked="" type="checkbox"/>	
Hard Hat <input checked="" type="checkbox"/>	No Loose Fitting Clothes <input checked="" type="checkbox"/>	Lights <u>OK</u>	Check plug in <input checked="" type="checkbox"/>	Test <input checked="" type="checkbox"/>	
Steel Toe Shoe <input checked="" type="checkbox"/>	No Sleeveless Shirts <input checked="" type="checkbox"/>	Windshield <u>OK</u>	Make sure it is working <input checked="" type="checkbox"/>	Rig Inspection <input checked="" type="checkbox"/>	
		Oil <u>OK</u>	Pull test tube <input checked="" type="checkbox"/>		



Key Energy Services

FOUR CORNERS
P.O. BOX 900
FARMINGTON, NM 87499 RIG NO. 8

114959

DATE: 3-19-02

COMPANY STATE OF NEW MEXICO
LEASE FANNY WARD
WELL NUMBER #1
STATE / COUNTY N.M. | SAN JUAN
SEC. 18 T/S 30N RANGE 11W
LOG. 36°-48'-62" N LAT. 108°-02'-12" W

FROM	TO	WORKOVER 1322	COMPLETION 6235	WELL CODE	CODE
6:00	7:00				
7:00	7:30				m
7:30	8:30				
8:30	9:00				
9:00	10:00				
10:00	11:00				
11:00	11:30				
11:30	12:30				
12:30	1:00				
1:00	2:30				

BA/NO.	CODE	COST	CODE	SALES ITEMS	QTY	PRICE EA.	COST	DOWN HOLE EQUIP.
152405	Pickup # Phone #		142325	S. Stripping Rubber				SIZE COUNT
121945	Rec. Stripping Head		142325	R. Stripping Rubber				TGB 278 211
121865	Companion Flange		142305	27/8 Swab Cups				Rods
121820	3000 BOP		142305	2.00 Swab Cups				Rods
121825	5000 BOP		142305	Other Swab Cups				Rods
132215	Power Rod or Tubing Tongs		142310	Oil Saver Rubbers				Rods
121705	2.5 Power Swivel Use Standby		142326	B.J. Tongs Dies				Subs
121710	3.5 Swivel		142326	Peckomatic Tong Dies				Polish Rod
121605	Pump Used Standby		142326	Slip Segments			331316	Fuel Surcharge \$
121910	Pit		162506	Pipe Dope				
121970	Pipe Racks		142315	Wiper Rubbers				
132210	Tong Heads Size							
132260	Slips 1 1/4 1 1/2 2 1/8 3 1/2 4 1/2							
132005	LYT Elevators			RIG TIME Hours		Rate \$		\$
132005	3 1/2 or 4 1/2 Elev.			RIG TIME Hours	6	Rate \$		\$
121850	BOP Rams - Additional		111585	TRAVEL TIME Hours	1 1/2	Rate \$		\$
132245	Rod Fishing Tools		111575	FLOW TIME				Accident
132246	Paraffin Knife			EMPLOYEE TIME	Hours	S.S. NO.		Y N
132125	Light Plant		Oper.	Jorge Montoya	7 1/2	585-44-6671		
121905	T.I.W. Valve		DK. Man	Freddy Archuleta	7 1/2	521-98-1860		
121845	Closing Unit		F.H.	LEAR CRUZ	7 1/2	510-74-1165		
132130	H2S Equipment		F.H.	Pete T. Archuleta	7 1/2	524-96-2940		
132110	Rig Ramp		F.H.					
111550	Subsistence		F.H.					
132255	Standing Valve							TOTAL DAILY COST \$
132115	Phone			Operators Signature				
162535	Restroom			Pusher Signature				
132220	Depthometer			Accepted By				
331315	Environmental Waste Surcharge			A.F.E. No.				
111510	Supervisor							

TRIP OUT <u>20</u>	TRIP OUT	TOTAL MAN HOURS <u>30</u>
TRIP IN <u>211</u>	TRIP IN	TRIP IN <u>20</u>
TRIP OUT	TRIP OUT	TRIP OUT <u>201</u>
TUBING SIZE	ROD SIZES	TOTAL FOOTAGE

SAFETY & ENVIRONMENTAL TOPIC
 COMMENTS: Read Employee Safety Hand book 32 & 33 All bottles are to have a safety ring or latch installed and functioning properly
 NEAR MISSES:
 POTENTIAL HAZARDS:

ODOMETER READING: 106629 PROPANE:
 ROUND TRIP MILEAGE: 55 RIG HIGHWAY MILEAGE:
 WEATHER: good ROAD CONDITIONS: good

DAILY SAFETY CHECK LIST		WALK AROUND PICKUP INSPECTION		B.O.P.	
Safety Glasses <input checked="" type="checkbox"/>	Personal Protective Equip <input checked="" type="checkbox"/>	Tires <input checked="" type="checkbox"/>	Check H2S Monitor <input checked="" type="checkbox"/>	Drill <input checked="" type="checkbox"/>	
Hard Hat <input checked="" type="checkbox"/>	No Loose Fitting Clothes <input checked="" type="checkbox"/>	Lights <input checked="" type="checkbox"/>	Check plug in <input checked="" type="checkbox"/>	Test <input checked="" type="checkbox"/>	
Steel Toe Shoe <input checked="" type="checkbox"/>	No Sleeveless Shirts <input checked="" type="checkbox"/>	Windshield <input checked="" type="checkbox"/>	Make sure it is working <input checked="" type="checkbox"/>	Rig Inspection <input checked="" type="checkbox"/>	
		Oil <input checked="" type="checkbox"/>	Pull test tube <input checked="" type="checkbox"/>		



Key Energy Services

FOUR CORNERS
P.O. BOX 900
FARMINGTON, NM 87499

114960

RIG NO. 8 DATE: 3-20-02

COMPANY STATE OF NEW MEXICO
LEASE FANNY WARD
WELL NUMBER #1
STATE / COUNTY N.M. / San Juan
SEC. 18 T/S 30N RANGE 11W
LOG. 36°-48'-62N LAT. 108°-02'-12W

FROM	TO	WORKOVER 1322	COMPLETION 6235	WELL CODE	CODE
6:00	7:00				
7:00	7:30				IN
7:30	8:00				
8:00	8:30				
8:30	9:00				
9:00	10:00				
10:00	11:00				
11:00	12:00				
12:00	12:30				
12:30	1:30				
1:30	4:00				
4:00	5:30				
5:30	6:00				

BA/NO.	CODE	COST	CODE	SALES ITEMS	QTY	PRICE EA.	COST	DOWN HOLE EQUIP.
	152405		142325	S. Stripping Rubber				SIZE
	121945		142325	R. Stripping Rubber				COUNT
	121865		142305	27/8 Swab Cups				TGB <u>238</u> <u>208</u>
	121820		142305	2.00 Swab Cups				Rods
	121825		142305	Other Swab Cups				Rods
	132215		142310	Oil Saver Rubbers				Rods
	121705		142326	B.J. Tongs Dies				Subs
	121710		142326	Peckomatic Tong Dies				Polish Rod
	121605		142326	Slip Segments			331316	Fuel Surcharge \$
	121910		162506	Pipe Dope				
	121970		142315	Wiper Rubbers				
	132210							
	132260							
	132005			RIG TIME Hours		Rate \$		\$
	132005			RIG TIME Hours	<u>10 1/2</u>	Rate \$		\$
	121850		111585	TRAVEL TIME Hours	<u>1 1/2</u>	Rate \$		\$
	132245		111575	FLOW TIME				Accident
	132246			EMPLOYEE TIME	Hours	S.S. NO.	Y	N
	132125		Oper.	<u>Lupe Montoya</u>	<u>12</u>	<u>535-446671</u>		
	121905		DK. Man	<u>Preddy Archulate</u>	<u>12</u>	<u>521-98-1860</u>		
	121845		F.H.	<u>CESAR CRUZ</u>	<u>12</u>	<u>510-74-1165</u>		
	132130		F.H.	<u>Pete Archulate</u>	<u>9 1/2</u>	<u>524-96-7940</u>		
	132110		F.H.					\$
	111550		F.H.					\$
	132255							TOTAL DAILY COST \$
	132115			Operators Signature	<u>Lupe Montoya</u>			
	162535			Pusher Signature	<u>JH</u>			
	132220			Accepted By				
	331315			A.F.E. No.				
	111510							

TRIP OUT <u>208</u>	TRIP OUT	TOTAL MAN HOURS <u>45 1/2</u>
TRIP IN	TRIP IN	TRIP IN <u>208</u>
TRIP OUT	TRIP OUT	TRIP OUT
TUBING SIZE	ROD SIZES	TOTAL FOOTAGE
SAFETY & ENVIRONMENTAL TOPIC Person Conducting Meeting <u>Lupe Montoya</u> COMMENTS: <u>Read Employee Safety Handbook page 34 and 35 while running in the hole sandline, stay off the rig floor.</u>		
NEAR MISSES:		
POTENTIAL HAZARDS:		

ODOMETER READING:	PROPANE:
ROUND TRIP MILEAGE:	RIG HIGHWAY MILEAGE:
WEATHER:	ROAD CONDITIONS:
DAILY SAFETY CHECK LIST	WALK AROUND PICKUP INSPECTION
Safety Glasses <input checked="" type="checkbox"/>	Tires <input checked="" type="checkbox"/>
Personal Protective Equip <input checked="" type="checkbox"/>	Lights <input checked="" type="checkbox"/>
Hard Hat <input checked="" type="checkbox"/>	Windshield <input checked="" type="checkbox"/>
Steel Toe Shoe <input checked="" type="checkbox"/>	Oil <input checked="" type="checkbox"/>
No Loose Fitting Clothes <input checked="" type="checkbox"/>	Check H2S Monitor <input checked="" type="checkbox"/>
No Sleeveless Shirts <input checked="" type="checkbox"/>	Check plug in <input checked="" type="checkbox"/>
	Make sure it is working <input checked="" type="checkbox"/>
	Pull test tube <input checked="" type="checkbox"/>
	Drill Test <input checked="" type="checkbox"/>
	Rig Inspection <input checked="" type="checkbox"/>



114961

Key Energy Services

FOUR CORNERS
P.O. BOX 900
FARMINGTON, NM 87499

RIG NO. 8 DATE: 3-21-02

COMPANY STATE OF NEW MEXICO

LEASE MANNY WAID

WELL NUMBER #1

STATE / COUNTY N.M. | SAN JUAN

SEC. 19 T/S 30W RANGE 11W

LOG. 76°-48'-42" W LAT. 105°-02'-12" W

FROM	TO	<input type="checkbox"/> WORKOVER 1322	<input type="checkbox"/> COMPLETION 6235	WELL CODE	CODE
6:00	7:00				
TRAVEL CRUE TO LOC					
7:00	7:30				
HAVE A. SAFETY MEETING					
7:30	8:00				
RIG UP WIRELINE AND SHOT AT 1275					
8:00	9:30				
T.I.H. WITH CEMENT RETAINER AND 19 STAND & PICKUP 1 JUNT					
9:30	10:00				
CERS AND CEMENT SACK					
10:00	11:00				
T.O.H. LAY DOWN 39 JUNT					
11:00	12:00				
RIG UP WIRELINE AND SHOT AT 545					
12:00	1:30				
CERS MUD OUT					
1:30	3:00				
WAITING ON WATER TRUCK					
3:00	4:30				
CERS AND CEMENT PUT IN 28 SACKET					
4:30	5:00				
RIG DOWN FLOOR AND DIG SAKER AND CUT WELL HEAD					
5:00	5:30				
RIG DOWN					
6:00	6:30				
TRAVEL CRUE TO YARD					

BA/NO.	CODE	COST	CODE	SALES ITEMS	QTY	PRICE EA.	COST	DOWN HOLE EQUIP.
	152405		142325	S. Stripping Rubber				SIZE
	121945		142325	R. Stripping Rubber				COUNT
	121865		142305	27/8 Swab Cups				TGB
	121820		142305	2.00 Swab Cups				Rods
	121825		142305	Other Swab Cups				Rods
	132215		142310	Oil Saver Rubbers				Rods
	121705		142326	B.J. Tongs Dies				Subs
	121710		142326	Peckomatic Tong Dies				Polish Rod
	121605		142326	Slip Segments				Fuel Surcharge \$
	121910		162506	Pipe Dope	1		331316	
	121970		142315	Wiper Rubbers				
	132210			Tong Heads				
	132260			Slips 1 1/4 1 1/2 2 1/16 3 1/2 4 1/2				
	132005			LYT Elevators				
	132005			3 1/2 or 4 1/2 Elev.				
	121850		111585	BOP Rams - Additional				
	132245		111575	Rod Fishing Tools				Accident
	132246			Paraffin Knife				Y N
	132125			Light Plant				
	121905			T.I.W. Valve				
	121845			Closing Unit				
	132130			H2S Equipment				
	132110			Rig Ramp				
	111550			Subsistence				
	132255			Standing Valve				
	132115			Phone				
	162535			Restroom				
	132220			Depthometer				
	331315			Environmental Waste Surcharge				
	111510			Supervisor				

OPERATORS SIGNATURE: [Signature] TOTAL DAILY COST \$

PUSHER SIGNATURE: [Signature]

ACCEPTED BY: _____

A.F.E. No. _____

TRIP OUT	TRIP IN	TOTAL MAN HOURS
TRIP IN	TRIP OUT	TRIP IN
TRIP OUT	TRIP IN	TRIP OUT
TUBING SIZE	ROD SIZES	TOTAL FOOTAGE

SAFETY & ENVIRONMENTAL TOPIC: Person Conducting Meeting

COMMENTS: Read Employee Safety Handbook page 35 and 36
Do not use a pipe wrench smaller than 48" as a tubing tong backup

NEAR MISSES: _____

POTENTIAL HAZARDS: _____

ODOMETER READING: _____ PROPANE: _____

ROUND TRIP MILEAGE: _____ RIG HIGHWAY MILEAGE: _____

WEATHER: good ROAD CONDITIONS: good

DAILY SAFETY CHECK LIST		WALK AROUND PICKUP INSPECTION		B.O.P.	
Safety Glasses <input checked="" type="checkbox"/>	Personal Protective Equip <input checked="" type="checkbox"/>	Tires <u>OK</u>	Check H2S Monitor <input checked="" type="checkbox"/>	Drill Test <input checked="" type="checkbox"/>	
Hard Hat <input checked="" type="checkbox"/>	No Loose Fitting Clothes <input checked="" type="checkbox"/>	Lights <u>OK</u>	Check plug in <input checked="" type="checkbox"/>	Rig Inspection <input checked="" type="checkbox"/>	
Steel Toe Shoe <input checked="" type="checkbox"/>	No Sleeveless Shirts <input checked="" type="checkbox"/>	Windshield <u>OK</u>	Make sure it is working <input checked="" type="checkbox"/>		
		Oil <u>OK</u>	Pull test tube <input checked="" type="checkbox"/>		

san juan reproduction 525-41



Key Energy Services

FOUR CORNERS
P.O. BOX 900
FARMINGTON, NM 87499 RIG NO. 8

114962

DATE: 3-22-02

COMPANY State of New Mexico
LEASE FANNY WARD
WELL NUMBER #1
STATE / COUNTY N.M. / Santa Fe
SEC. 18 T/S 30W RANGE 11W
LOG. 36-48-62 N. LAT. 108-02-12W

FROM	TO	<input type="checkbox"/> WORKOVER 1322	<input type="checkbox"/> COMPLETION 6235	WELL CODE	CODE
6:00	7:00				
7:00	7:30				
7:30	8:00				
		Travel time to loc			
		Have H. Safety Meeting			
		Move OEP of LOE			

BA/NO.	CODE	COST	CODE	SALES ITEMS	QTY	PRICE EA.	COST	DOWN HOLE EQUIP.
152405	Pickup # Phone #		142325	S. Stripping Rubber				SIZE COUNT
121945	Rec. Stripping Head		142325	R. Stripping Rubber				TGB
121865	Companion Flange		142305	27/8 Swab Cups				Rods
121820	3000 BOP		142305	2.00 Swab Cups				Rods
121825	5000 BOP		142305	Other Swab Cups				Rods
132215	Power Rod or Tubing Tongs		142310	Oil Saver Rubbers				Rods
121705	2.5 Power Swivel Use Standby		142326	B.J. Tongs Dies				Subs
121710	3.5 Swivel		142326	Peckomatic Tong Dies				Polish Rod
121605	Pump Used Standby		142326	Slip Segments				Fuel Surcharge \$
121910	Pit		162506	Pipe Dope			331316	
121970	Pipe Racks		142315	Wiper Rubbers				
132210	Tong Heads Size							
132260	Slips 1 1/4 1 1/2 2 1/16 3 1/2 4 1/2							
132005	LYT Elevators			RIG TIME Hours		Rate \$		\$
132005	3 1/2 or 4 1/2 Elev.			RIG TIME Hours	1	Rate \$		\$
121850	BOP Rams - Additional		111585	TRAVEL TIME Hours	1	Rate \$		\$
132245	Rod Fishing Tools		111575	FLOW TIME				Accident
132246	Paraffin Knife			EMPLOYEE TIME	Hours	S.S. NO.		Y N
132125	Light Plant		Oper.	Lupe Montoya	2	585-44-1671		
121905	T.I.W. Valve		DK. Man	Freddy Archilote	2	521-48-1860		
121845	Closing Unit		F.H.	Cesar Cruz	2	510-74-1165		
132130	H2S Equipment		F.H.	Trinidad Concia	2	457-44-7593		
132110	Rig Ramp		F.H.	Trinidad Concia		524-94-5990		
111550	Subsistence		F.H.					
132255	Standing Valve							TOTAL DAILY COST \$
132115	Phone							Operators Signature <u>Lupe Montoya</u>
162535	Restroom							Pusher Signature <u>JA</u>
132220	Depthometer							Accepted By _____
331315	Environmental Waste Surcharge							A.F.E. No. _____
111510	Supervisor							

TRIP OUT	TRIP OUT	TOTAL MAN HOURS
TRIP IN	TRIP IN	TRIP IN
TRIP OUT	TRIP OUT	TRIP OUT
TUBING SIZE	ROD SIZES	TOTAL FOOTAGE
SAFETY & ENVIRONMENTAL TOPIC COMMENTS: <u>Redd Employee Safety Hand book page 35 and 36</u> Person Conducting Meeting <u>Lupe Montoya</u>		
NEAR MISSES:		
POTENTIAL HAZARDS:		
ODOMETER READING: _____	PROPANE: _____	
ROUND TRIP MILEAGE: _____	RIG HIGHWAY MILEAGE: _____	
WEATHER: <u>good</u>	ROAD CONDITIONS: <u>good</u>	
DAILY SAFETY CHECK LIST	WALK AROUND PICKUP INSPECTION	B.O.P.
Safety Glasses <input checked="" type="checkbox"/>	Tires <u>OK</u>	Drill <u>1</u>
Personal Protective Equip <input checked="" type="checkbox"/>	Lights <u>OK</u>	Test <u>1</u>
Hard Hat <input checked="" type="checkbox"/>	Windshield <u>OK</u>	Rig Inspection <u>1</u>
No Loose Fitting Clothes <input checked="" type="checkbox"/>	Oil <u>OK</u>	
No Sleeveless Shirts <input checked="" type="checkbox"/>	Check H2S Monitor <u>1</u>	
	Check plug in <u>1</u>	
	Make sure it is working <u>1</u>	
	Pull test tube <u>1</u>	

L&R OILFIELD SERVICE

3204 Southside River Rd
Farmington, NM 87401-7967
505-325-1922
FAX 505-327-2537

Invoice

DATE	INVOICE #
5/10/2002	8372

BILL TO
KEY ENERGY PO BOX 900 FARMINGTON NM 87499-0900 JOE DAVIS

VENDOR NO.	TERMS
8041	

DATE	DESCRIPTION	AMOUNT
5/10/2002	FANNIE WARD #1 CULVERT INSTALLATION. Tax Exempt	688.77 0.00
Total		\$688.77

TERMS: Net 30 Days. Interest Charged at the Rate of
2% PER MONTH or 24% PER ANNUM on Accounts
not paid within 30 days.



L & R OILFIELD SERVICE

3204 Southside River Road
 Farmington, NM 87401
 (505) 325-1922

Company: <i>Key Energy</i>	Date: <i>05-10-02</i>
City:	State:
Lease: <i>FANNIE WARD</i>	Well No.: <i># 1</i>
Run Number:	
AFE:	AO:
Foreman: <i>Joe Davis</i>	Lease Operator:

Quan.	Description	Price	Amount		No.	Hours	Rate	Amount
1	ROAD BASE ^{TICKET} #17122		27 82	Foreman <i>MAURICE</i>	261	6 1/2	22.00	143 00
1	ROAD BASE #17131		22 45	Labor <i>ROGER B.</i>		6 1/2	17.50	113 75
				Labor <i>Felix S.</i>		6 1/2	17.50	113 75
1	20' Culvert	N/C		Labor				
				Mechanic				
				Mechanic's Helper				
				Pumper				
				Welders w/Rig				
				Welder's Helper				
				1/2 Ton Pickup				
				3/4 Ton Pickup				
				1 Ton Pickup				
				2 Ton Pickup	<i>T-47</i>	6 1/2	22.00	143 00
				Backhoe	<i>H-41</i>	2	27.00	54 00
				Float Trailer	<i>F-138</i>	2	205.00	410 00
				Tank Skid				
				Dump Box		6 1/2 day		25 00
				Paint Rig				
				Other <i>gravel</i>				50 27
				Parts				
Sub-Total								688 77
Tax								
TOTAL								

Pre Job Safety Meeting:
Body position, BACKLICE OPERATIONS
pinch points

Time Out: *7:00* Time In: *1:30 P.M.*

Description of Work:
LOADED DUMP BOX AND BACKLICE DRUMS TO
NEWCO PICKED UP ROAD BASE DROVE TO JOB SITE
UNLOADED BACKHOE AND DUMP BOX INSTALLED CULVERT
IN TRENCH BACK FILLED WITH ROAD BASE. DROVE TO
NEWCO TO PICK UP MORE ROAD BASE HAVED TO JOB
SITE FILLED AROUND CULVERT AND PACKED BACKPACKAGED AREA
LOADED BACKLICE & DUMP BOX DROVE TO YARD

SIGNED BY: *[Signature]*

[Signature]

ENVIROTECH INC.

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

Customer# 98065
Invoice # 6995
Invoice Date: 03/29/02
Due Date: 04/28/02

Key Energy, Inc.
Attn: Nathan Crawford
PO Box 900
Farmington, NM 87499

Job # 98065-005

Change Order:
Surface cleanup and pit closure of the Fannie Ward #1 Well, 18-30N-11W, Aztec NM

Remove trees	\$ 200.00
Remove cement	100.00

Subtotal: \$ 300.00
NMGRT: ~~17.25~~
Total Due: \$ 317.25

PAID
CK. NO. 134077 \$ 5604.75
DATE 5/20/02

Thank you for your business!

Please send copy of invoice with payment. Delinquent accounts will be charged 1.5%

ENVIROTECH INC.

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

Customer# 98065
Invoice # 6994
Invoice Date: 03/29/02
Due Date: 04/28/02

Key Energy, Inc.
Attn: Nathan Crawford
PO Box 900
Farmington, NM 87499

Job # 98065-005

Surface cleanup and pit closure of the Fannie Ward #1 Well, 18-30N-11W, Aztec NM

Contract price	\$ 4,550.00
Asbestos sampling and removal from two dehydrator units	<u>450.00</u>

Subtotal: \$ 5,000.00
NMGRT: ~~287.50~~
Total Due: \$ 5,287.50

NA

PAID
CK. NO. 134077 5004.75
DATE 5/20/02

Thank you for your business!

Please send copy of invoice with payment. Delinquent accounts will be charged 1.5%

ENVIROTECH INC.

Bill of Lading

PHONE: (505) 632-0615 • 5796 U.S. HIGHWAY 64 • FARMINGTON, NEW MEXICO 87401

JOB # 42954 98065-005

DATE 3-20-02

MANIFEST NO.	COMPLETE DESCRIPTION OF SHIPMENT					TRANSPORTING COMPANY				
	POINT OF ORIGIN	DESTINATION	MATERIAL	GRID	YDS	BBLS	COMPANY	TRK#	TIME	DRIVER SIGNATURE
1	State of NM Farmville Road #1	#2	Drilling mud water	UIS		80	Kcy	557	3:05 pm	[Signature]

RECEIVED MAR 21 2002

"I certify the material hauled from the above location has not been added to or mixed with, and is the same material received from the above mentioned Generator, and that no additional materials have been added."

NAME Mike Hare COMPANY Envirotech SIGNATURE Mike Hare DATE 3-20-02

To Re-order Call 325-9600 or Fax 325-9764 8000179101 FORM 9 01

ENVIROTECH INC.

2007 2 2 WAD RECEIVED
 Bill of Lading JOB #

12997

PHONE: (505) 632-0615 • 5796 U.S. HIGHWAY 64 • FARMINGTON, NEW MEXICO 87401

DATE

032202

MANIFEST

COMPLETE DESCRIPTION OF SHIPMENT

TRANSPORTING COMPANY

NO.	POINT OF ORIGIN	DESTINATION	MATERIAL	GRID	YDS	BBLs	COMPANY	TRK#	TIME	DRIVER SIGNATURE
1	KEY-FRAME WYED	FRAM #2	liquids	V17		80	KEY	1526	0940	[Signature]
2	KEY-FRAME WYED	FRAM #2	liquids	V17		80	KEY	1557	0940	James [Signature]
3	KEY-FRAME WYED	FRAM #2	liquids	V17		40	KEY	1557	1200	James [Signature]
BILLED APR 30 2002										

"I certify the material hauled from the above location has not been added to or mixed with, and is the same material received from the above mentioned Generator, and that no additional materials have been added."

NAME

[Signature]

COMPANY

EnviroTech

SIGNATURE

[Signature]

DATE

032202

ENVIROTECH INC.

Bill of Lading

98065-05

13019

PHONE: (505) 632-0615 • 5796 U.S. HIGHWAY 64 • FARMINGTON, NEW MEXICO 87401

JOB # _____

DATE 3-21-02

MANIFEST

COMPLETE DESCRIPTION OF SHIPMENT

TRANSPORTING COMPANY

NO.	POINT OF ORIGIN	DESTINATION	MATERIAL	GRID	YDS	BBL'S	COMPANY	TRK#	TIME	DRIVER SIGNATURE
	Frankie David #1 Ker Energy	LFZ	Com out	V-15		18	KEY	1530	17:20x	Jerry Hennessy

ENTERED MAR 22 2002

RECEIVED MAR 22 2002

"I certify the material hauled from the above location has not been added to or mixed with, and is the same material received from the above mentioned Generator, and that no additional materials have been added."

NAME Harold W. Brasow COMPANY Enviro Tech SIGNATURE Harold W. Brasow

DATE 3-21-02



Key Energy Services, Inc.

P.O. Box 900
5651 US Highway 64
Farmington, NM 87499
505-327-0416 • Fax 505-327-4962

185868

DATE: 3/20/02

CUSTOMER: Stat Ann BILL TO LOCATION: Fanny Ward #1 RIG & NO.: Key Rig #8
 FROM: Rig Pit TO: Key Disp 75910 COUNTY: ST
 WORK ACTIVITY: Pull Pit DRIVER: James McLaughlin TRUCK #: 1520
 COMPANY MAN: LEGAL: SECTION: 18 TOWNSHIP: 30 RANGE: 11

PERSONAL PROTECTIVE EQUIPMENT REQUIRED AND/OR RECOMMENDED:
 ALL PPE REQUIRED, SAFETY GLASSES, HARD HAT, STEEL TOES, 100% COTTON OUTER CLOTHING REQUIRED, COTTON GLOVES, SEAT BELTS, TIRE CHAINS AS REQUIRED

SEQUENCE OF BASIC JOB STEPS	POTENTIAL ACCIDENTS OR HAZARDS	RECOMMENDED SAFE JOB PROCEDURES
DRIVING TO LOCATION	<u>watch for school bus</u>	<u>Drive Safe</u>
GAUGING TANKS OR PITS	<u>watch for stop</u>	<u>use handrail</u>
HOOKING UP/WALK AROUND, CHECK VALVES	<u>check for leaks</u>	<u>use backup</u>
LOADING OR UNLOADING	<u>look for leaks</u>	<u>see house dir</u>
UNHOOKING/WALK AROUND, CHECK FOR LEAKS	<u>water in house</u>	<u>Pull out line and house dir</u>
GAUGING TANKS OR PITS		
DRIVING FROM LOCATION	<u>Drive Safe</u>	
UNSCHEDULED EVENTS		

ENVIRONMENTAL CONDITION:
 DAY NIGHT CLEAR FOG DRIZZLE
 HUMID RAIN SNOW ICE DUST
 TEMP 32° OR LESS 32° TO 80° 80° OR MORE
 CHAIN REQ. HIGHWAY STEEP GRADES
 WIND/15 OR LESS 15-40 40 OR MORE
 MUD MODERATE DEEP DRIED

IS THIS LOCATION LOCKED AND TAGGED OUT? YES NO
 BY KEY REPRESENTATIVE? YES NO
 BY COMPANY REP.? YES NO

WORK AREA: OPEN TIGHT CONGESTED
 LOCATION
 ELEVATED
 BELOW GROUND LEVEL
 CONFINED SPACE
 GROUND LEVEL


BODY POSITION:
 CLIMBING PULLING PUSHING
 BENDING TWISTING TURNING
 STRETCHING REACHING JUMPING
 CROUCHING WALKING PINCH POINTS
 OTHER

	OIL	WATER	ROAD TIME OUT	STOP TIME	HRS.	SIGNATURE
1. BBLs. HAULED		<u>90</u>	<u>7:30</u> P.M.	<u>9:00</u> P.M.	<u>1.5</u>	<u>James McLaughlin</u>
2. BBLs. HAULED			START TIME	STOP TIME		REC'D BY
3. BBLs. HAULED			START TIME	STOP TIME		REC'D BY
4. BBLs. HAULED			START TIME	STOP TIME		REC'D BY
5. BBLs. HAULED			START TIME	STOP TIME		REC'D BY
6. BBLs. HAULED			START TIME	STOP TIME		REC'D BY
7. BBLs. HAULED			START TIME	STOP TIME		REC'D BY
8. BBLs. HAULED			START TIME	STOP TIME		REC'D BY
9. BBLs. HAULED			ROAD TIME IN	STOP TIME		REC'D BY

TOTAL BBLs.	<u>90</u>	HIGH GAUGE	TOTAL HOURS	<u>1.5</u>	<u>55.00</u> PER \$ <u>82.50</u>
		LOW GAUGE			FUEL SURCHARGE
REMARKS	<u>Pull out of Rig Pit</u>				ENVIRONMENTAL SURCHARGE <u>4.15</u>
					SUBTOTAL <u>87.95</u>
					TAX <u>4.77</u>
					TOTAL <u>87.70</u>

WERE THERE ANY ACCIDENTS OR SPILLS ON THIS JOB? YES NO DRIVER SIGNATURE X James McLaughlin

789100



Key Energy Services, Inc.
Four Corners

WATER DISPOSAL (505) 334-6186
County Road 3500 P.O. Box 900
Crouch Mesa Bypass Farmington, NM 87499

DATE 3-20-02
CUSTOMER State of N.M.
WELL NAME/NUMBER Jarvis ward #1
TRUCKING COMPANY Key
DRIVER McKnight UNIT NO. 15216
DELIVERY TICKET # 185868

KEY ENERGY SERVICES, INC. Reserves the right to refuse any material being hauled into this disposal.

LOAD	WATER	TIME	AM	PM	DRIVER SIGNATURE
1	80	8:40	/		<i>[Signature]</i>
2					
3					

- H₂S ___ ppm
- No H₂S
- Black
- Solid content 40%
- Non Exempt
- Waste Oil ___ bbls
- White Water Light Med Heavy

Load Description: Very Dirty drilling mud sample taken 80x6.75

1 Loads @ 540 = 540
31.05

Company Representative Signature Jimmy Bandster

Total = 571.05

san juan reproduction 291-26

QTY	HAULED	TIME	P.M.	TIME	P.M.	REC'D BY
4.	BBLs. HAULED	START TIME	A.M.	STOP TIME	A.M.	REC'D BY
5.	BBLs. HAULED	START TIME	A.M.	STOP TIME	A.M.	REC'D BY
6.	BBLs. HAULED	START TIME	A.M.	STOP TIME	A.M.	REC'D BY
7.	BBLs. HAULED	START TIME	A.M.	STOP TIME	A.M.	REC'D BY
8.	BBLs. HAULED	START TIME	A.M.	STOP TIME	A.M.	REC'D BY
9.	BBLs. HAULED	ROAD TIME IN	A.M.	STOP TIME	A.M.	REC'D BY
TOTAL BBLs.			HIGH GAUGE	TOTAL HOURS <u>2 1/2</u>		FUEL <u>55.00</u> PER \$ <u>137.50</u>
			LOW GAUGE			SURCHARGE
REMARKS						ENVIRONMENTAL SURCHARGE <u>75</u>
						SUBTOTAL <u>138.25</u>
						TAX <u>7.95</u>
						TOTAL <u>146.20</u>

WERE THERE ANY ACCIDENTS OR SPILLS ON THIS JOB? YES NO DRIVER SIGNATURE X [Signature]



Key Energy Services, Inc.

P.O. Box 900
5651 US Highway 64
Farmington, NM 87499
505-327-0416 • Fax 505-327-4962

182608

DATE: 3-21-02

CUSTOMER: P/A (KEY) BILL TO LOCATION: FANNIE WARD #1 RIG & NO: Key #8
 FROM: WEAH TO: ENVIROTECH INC COUNTY: S. J.
 WORK ACTIVITY: CMT DRIVER: LYNN THOMAS TRUCK #: 1030
 COMPANY MAN: LEGAL: SECTION: 18 TOWNSHIP: 30N RANGE: 11W

PERSONAL PROTECTIVE EQUIPMENT REQUIRED AND/OR RECOMMENDED:
 ALL PPE REQUIRED, SAFETY GLASSES, HARD HAT, STEEL TOES, 100% COTTON OUTER CLOTHING REQUIRED, COTTON GLOVES, SEAT BELTS, TIRE CHAINS AS REQUIRED

SEQUENCE OF BASIC JOB STEPS	POTENTIAL ACCIDENTS OR HAZARDS	RECOMMENDED SAFE JOB PROCEDURES
DRIVING TO LOCATION	WALK W/REAR VIEW MIRROR	DRIVE SAFE
GAUGING TANKS OR PITS	SLIP & FALL	WATCH WHERE YOU STEP
HOOKING UP/WALK AROUND, CHECK VALVES	VALVES OPEN	CHECK VALVES
LOADING OR UNLOADING		
UNHOOKING/WALK AROUND, CHECK FOR LEAKS	SLUNG HOSE FULL OF WATER	P/A HOSE DRY
GAUGING TANKS OR PITS		
DRIVING FROM LOCATION	DRIVE SAFE	
UNSCHEDULED EVENTS		

ENVIRONMENTAL CONDITION:
 DAY NIGHT CLEAR FOG DRIZZLE
 HUMID RAIN SNOW ICE DUST
 TEMP 32° OR LESS 32° TO 80° 80° OR MORE
 CHAIN REQ. HIGHWAY STEEP GRADES
 WIND/15 OR LESS 15-40 40 OR MORE
 MUD MODERATE DEEP DRIED

IS THIS LOCATION LOCKED AND TAGGED OUT? YES NO
 BY KEY REPRESENTATIVE? YES NO
 BY COMPANY REP.? YES NO

WORK AREA: OPEN TIGHT CONGESTED
 LOCATION
 ELEVATED
 BELOW GROUND LEVEL
 CONFINED SPACE
 GROUND LEVEL

BODY POSITION:
 CLIMBING PULLING PUSHING
 BENDING TWISTING TURNING
 STRETCHING REACHING JUMPING
 CROUCHING WALKING PINCH POINTS
 OTHER _____

	OIL	WATER	ROAD TIME OUT	STOP TIME	STOP TIME	HRS.	SIGNATURE
1. BBLs. HAULED		18	3:30 P.M.	6:30 P.M.		3	REC'D BY
2. BBLs. HAULED			START TIME	STOP TIME			REC'D BY
3. BBLs. HAULED			START TIME	STOP TIME			REC'D BY
4. BBLs. HAULED			START TIME	STOP TIME			REC'D BY
5. BBLs. HAULED			START TIME	STOP TIME			REC'D BY
6. BBLs. HAULED			START TIME	STOP TIME			REC'D BY
7. BBLs. HAULED			START TIME	STOP TIME			REC'D BY
8. BBLs. HAULED			START TIME	STOP TIME			REC'D BY
9. BBLs. HAULED			ROAD TIME IN	STOP TIME			REC'D BY
TOTAL BBLs.		18				3	
			HIGH GAUGE				55.00 PER \$ 165.00
			LOW GAUGE				FUEL SURCHARGE —
REMARKS							ENVIRONMENTAL SURCHARGE 90
							SUBTOTAL 165.90
							TAX 9.54
							TOTAL 175.44

WERE THERE ANY ACCIDENTS OR SPILLS ON THIS JOB? YES NO DRIVER SIGNATURE X Lynn Thomas



Key Energy Services, Inc.

P.O. Box 900
5651 US Highway 64
Farmington, NM 87499
505-327-0416 • Fax 505-327-4962

182677

DATE: 8 22 02

CUSTOMER: STATE OF NM BILL TO LOCATION: FARMY WATER 1 RIG & NO.: KEYRIG 8
 FROM: RIG PIT TO: ENCLOSURE HAND FARM COUNTY: ST
 WORK ACTIVITY: RUN PIT DRIVER: JAMES MURPHY TRUCK #: 1557
 COMPANY MAN: LEGAL: SECTION: 18 TOWNSHIP: 30 RANGE: 11

PERSONAL PROTECTIVE EQUIPMENT REQUIRED AND/OR RECOMMENDED:
 ALL PPE REQUIRED, SAFETY GLASSES, HARD HAT, STEEL TOES, 100% COTTON OUTER CLOTHING REQUIRED, COTTON GLOVES, SEAT BELTS, TIRE CHAINS AS REQUIRED

SEQUENCE OF BASIC JOB STEPS	POTENTIAL ACCIDENTS OR HAZARDS	RECOMMENDED SAFE JOB PROCEDURES
DRIVING TO LOCATION	<u>WAITING FOR SCHOOL BUS</u>	<u>DRIVE SAFE</u>
GAUGING TANKS OR PITS	<u>SLIPPING AND FALLING</u>	<u>USE HARD SHOES</u>
HOOKING UP/WALK AROUND, CHECK VALVES	<u>VALVES OPEN</u>	<u>CHECK VALVE</u>
LOADING OR UNLOADING	<u>NOT HAVING PUMP IN POST</u>	<u>CHECK PUMP</u>
UNHOOKING/WALK AROUND, CHECK FOR LEAKS	<u>WATER AT HOSE</u>	<u>PROTECT HOSE BODY</u>
GAUGING TANKS OR PITS		
DRIVING FROM LOCATION	<u>DRIVE SAFE</u>	
UNSCHEDULED EVENTS		

ENVIRONMENTAL CONDITION:
 DAY NIGHT CLEAR FOG DRIZZLE
 HUMID RAIN SNOW ICE DUST
 TEMP 32° OR LESS 32° TO 80° 80° OR MORE
 CHAIN REQ. HIGHWAY STEEP GRADES
 WIND/15 OR LESS 15-40 40 OR MORE
 MUD MODERATE DEEP DRIED

IS THIS LOCATION LOCKED AND TAGGED OUT? YES NO
BY KEY REPRESENTATIVE? YES NO
BY COMPANY REP.? YES NO

WORK AREA: OPEN TIGHT CONGESTED
 LOCATION
 ELEVATED
 BELOW GROUND LEVEL
 CONFINED SPACE
 GROUND LEVEL

BODY POSITION:
 CLIMBING PULLING PUSHING
 BENDING TWISTING TURNING
 STRETCHING REACHING JUMPING
 CROUCHING WALKING PINCH POINTS
 OTHER _____

	OIL	WATER	ROAD TIME OUT	STOP TIME	HRS.	SIGNATURE
1. BBLs. HAULED		<u>30</u>	<u>6:00</u> A.M. <u>10:00</u> P.M.	<u>10:00</u> A.M. <u>10:00</u> P.M.	<u>4</u>	REC'D BY
2. BBLs. HAULED		<u>40</u>	<u>10:00</u> A.M. <u>1:00</u> P.M.	<u>1:00</u> A.M. <u>1:00</u> P.M.	<u>3</u>	REC'D BY
3. BBLs. HAULED			START TIME A.M. P.M.	STOP TIME A.M. P.M.		REC'D BY
4. BBLs. HAULED			START TIME A.M. P.M.	STOP TIME A.M. P.M.		REC'D BY
5. BBLs. HAULED			START TIME A.M. P.M.	STOP TIME A.M. P.M.		REC'D BY
6. BBLs. HAULED			START TIME A.M. P.M.	STOP TIME A.M. P.M.		REC'D BY
7. BBLs. HAULED			START TIME A.M. P.M.	STOP TIME A.M. P.M.		REC'D BY
8. BBLs. HAULED			START TIME A.M. P.M.	STOP TIME A.M. P.M.		REC'D BY
9. BBLs. HAULED			ROAD TIME IN A.M. P.M.	STOP TIME A.M. P.M.		REC'D BY
TOTAL BBLs.			HIGH GAUGE	TOTAL HOURS	<u>7</u>	<u>55.00 PER \$ 385.00</u>
			LOW GAUGE			FUEL SURCHARGE

REMARKS

ENVIRONMENTAL SURCHARGE 2.10

SUBTOTAL 387.10

TAX 22.20

TOTAL 409.30

WERE THERE ANY ACCIDENTS OR SPILLS ON THIS JOB? YES NO DRIVER SIGNATURE X James Murphy



Key Energy Services, Inc.

P.O. Box 900
5651 US Highway 64
Farmington, NM 87499
505-327-0416 • Fax 505-327-4962

182701

DATE: 3/22/02

CUSTOMER: State of N.M. BILL TO LOCATION: Fanny Ward #1 RIG & NO.: N/A
 FROM: Rig - P. 1 TO: Eliminator Land Fill Area COUNTY: ST.
 WORK ACTIVITY: R.L. - Rig Pit DRIVER: James McKnight SR TRUCK #: 1526
 COMPANY MAN: LEGAL SECTION: 18 TOWNSHIP: 30 RANGE: 11

PERSONAL PROTECTIVE EQUIPMENT REQUIRED AND/OR RECOMMENDED:
 ALL PPE REQUIRED, SAFETY GLASSES, HARD HAT, STEEL TOES, 100% COTTON OUTER CLOTHING REQUIRED, COTTON GLOVES, SEAT BELTS, TIRE CHAINS AS REQUIRED

SEQUENCE OF BASIC JOB STEPS	POTENTIAL ACCIDENTS OR HAZARDS	RECOMMENDED SAFE JOB PROCEDURES
DRIVING TO LOCATION	Watch for school bus	Drive safe
GAUGING TANKS OR PITS	Watch for step	use handrails
HOOKING UP/WALK AROUND, CHECK VALVES	watch for leaks	use parking
LOADING OR UNLOADING	Check for leaks	See how to
UNHOOKING/WALK AROUND, CHECK FOR LEAKS	water in house	see how to
GAUGING TANKS OR PITS		
DRIVING FROM LOCATION	Drive safe	
UNSCHEDULED EVENTS		

ENVIRONMENTAL CONDITION:
 DAY NIGHT CLEAR FOG DRIZZLE
 HUMID RAIN SNOW ICE DUST
 TEMP 32° OR LESS 32° TO 80° 80° OR MORE
 CHAIN REQ. HIGHWAY STEEP GRADES
 WIND/15 OR LESS 15-40 40 OR MORE
 MUD MODERATE DEEP DRIED

IS THIS LOCATION LOCKED AND TAGGED OUT? YES NO
 BY KEY REPRESENTATIVE? YES NO
 BY COMPANY REP.? YES NO
WORK AREA: OPEN TIGHT CONGESTED
 LOCATION
 ELEVATED
 BELOW GROUND LEVEL
 CONFINED SPACE
 GROUND LEVEL

BODY POSITION:
 CLIMBING PULLING PUSHING
 BENDING TWISTING TURNING
 STRETCHING REACHING JUMPING
 CROUCHING WALKING PINCH POINTS
 OTHER

	OIL	WATER	ROAD TIME	STOP TIME	HRS.	SIGNATURE
1. BBLs. HAULED		30	6:00 A.M.	10:00 P.M.	4	REC'D BY
2. BBLs. HAULED			START TIME	STOP TIME		REC'D BY
3. BBLs. HAULED			START TIME	STOP TIME		REC'D BY
4. BBLs. HAULED			START TIME	STOP TIME		REC'D BY
5. BBLs. HAULED			START TIME	STOP TIME		REC'D BY
6. BBLs. HAULED			START TIME	STOP TIME		REC'D BY
7. BBLs. HAULED			START TIME	STOP TIME		REC'D BY
8. BBLs. HAULED			START TIME	STOP TIME		REC'D BY
9. BBLs. HAULED			ROAD TIME IN	STOP TIME		REC'D BY

TOTAL BBLs.	80	HIGH GAUGE	TOTAL HOURS	4	\$55.00 PER	\$ 220.00
		LOW GAUGE			FUEL SURCHARGE	-
REMARKS					ENVIRONMENTAL SURCHARGE	1.20
					SUBTOTAL	221.20
					TAX	12.72
					TOTAL	233.92

WERE THERE ANY ACCIDENTS OR SPILLS ON THIS JOB? YES NO **DRIVER SIGNATURE X**



OLDCASTLE SW GROUP, INC.

INVOICE

Invoice No: 124851
 Invoice Date: 3/16/02
 Customer No: 3510
 Job Number: CR# 3133

Four Corners Materials
 P.O. Box 16
 Farmington, NM 87499
 (505) 324-3910

Key Energy Group-Four Corners
 PO Box 900
 Farmington, NM 87499-0900

Location/Delivery Address:
 CR# 3133
 FLORA VISTA

Date	Item	Description	Quantity	UM	Unit Price	Material Total	Tax Code	Tax	Total
Ticket #: 245821									
From: Farmington Ready Mix									
3/13/02	35233002	3000 3/4" 18% FAWR Air	8.000	CY	68.75 E	550.00	NM14	0.00	550.00
3/13/02	69.CC2	1% Calcium	8.000	CY	2.50 E	20.00	NM14	0.00	20.00
3/13/02	69.CC4	2% Calcium	8.000	CY	5.00 E	40.00	NM14	0.00	40.00
3/13/02	89.HW	Hot Water	8.000	CY	3.00 E	24.00	NM14	0.00	24.00
Total						634.00		0.00	634.00
Total Invoice:						634.00		0.00	634.00

Total Cubic Yards of Readymix for this invoice 8.00

TERMS OF PAYMENT: Payment is due 30 days from the date of invoice. A 2% discount will be given to all customers whose payments are received or postmarked no later than the 10th of the month, following the month of purchase. In the event payment is not made when due, reasonable collection fees, lien fees, and attorney fees with or without suit, together with 1-1/2% per month SERVICE CHARGE, which is an ANNUAL PERCENTAGE RATE of 18%, will be assessed until paid.

PLEASE PAY FROM THIS INVOICE-DETACH AND RETURN WITH PAYMENT

Remit to: Four Corners Materials
 P.O. Box 16
 Farmington, NM 87499

Customer Name: Key Energy Group-Four Corners
 Customer No: 3510
 Invoice No: 124851
 Invoice Amount: 634.00

Amount Remitted: _____