

# FIELD INSPECTION FORM FOR WELLS TO BE PLUGGED

DATE INSPECTED 5-4-98

BY Raymond

OPERATOR: Southwest Production

PROPERTY NAME & #: Fannie Ward #1

FOOTAGE: 1800 ESL + 1520 FWL

LOCATION: UL: K SEC: 18 TWN: 30N RGE: 11W

POOL/S: Basin Dakota

API# 30-045-09481

WERE PHOTOGRAPHS TAKEN? Yes

NUMBER: \_\_\_\_\_

DESCRIPTION OF SUBJECT ON PHOTOGRAPH: Picture of well, Battery & Separator

## INVENTORY

DESCRIPTION OF WELLHEAD: Brackish, x-man tree with 2 3/4" x 7 1/2"

Copperhead Battery on site. Copperhead 2000 PSI 2 x 1 3/4" x 1 1/2"

looking up

SURFACE: \_\_\_\_\_ INTERMEDIATE: \_\_\_\_\_ PROD CSG: \_\_\_\_\_

TBG: \_\_\_\_\_ RODS: \_\_\_\_\_

PRODUCTION EQUIPMENT: \_\_\_\_\_

TANKS: separator Column 4000 lbs. 12-12 NSG, WP 125 PSI

# 100-4, Test 255 2000 PSI of 7/11/98 11-66

Material Tank 210 lbs. welded

1-4-3-16 Ser E 18287

6" BS

## DESCRIPTION OF PITS

None