

C O P Y


(SUBMIT IN TRIPLICATE)

Land Office Santa Fe

Lease No. 080601

Unit _____

**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	Casing Report	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 12, 1958

Federal "V" San Juan Lease

Well No. 1-14 is located 1770 ft. from N E line and 1610 ft. from E W line of sec. 14

SE/4 NE/4 Sec. 14 30 N 11 W N. M. P. M.
(¼ Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Astec Pictured Cliffs San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5906 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This test spudded January 31, 1958.

On that same day 9 5/8" surface pipe was set at 111' with 100 sacks. This pipe was tested at 500 pounds pressure for 30 minutes with no pressure drop, before drilling ahead.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company John H. Trigg

Address P. O. Box 5629

Roswell, New Mexico

By signed by Co. Geologist

Title _____