Denny & Fruit DEPUTY OR & GAS INSPECTION

DEC 22 1997

Meter Number:73043 Location Name:MADDOX WN FEDERAL #1 Location:TN-30 RG-13 SC-13 UL-H

> 2 - Federal NMOCD Zone: OUTSIDE Hazard Ranking Score: 00

PECELLA MARKA 1 4 1997 1997

(1) MOD 11U 8. Jena

### RATIONALE FOR RISK-BASED CLOSURE OF PRODUCTION PITS LOCATED OUTSIDE OF THE VULNERABLE ZONE IN THE SAN JUAN BASIN

This production pit location was ranked according to the criteria in the New Mexico Oil Conservation Division's Unlined Surface Impoundment Closure Guidelines and received a ranking score of zero. The estimated depth to groundwater is greater than 100-feet beneath ground surface (bgs), the pit is not in a well head protection area, and there are no surface water bodies within 1,000 horizontal feet of the pit location.

The primary source, discharge to the pit has been removed. There has been no discharge to the pits for at least 4 years and the pits have been closed for at least one year.

Each pit was backfilled with clean soil and graded in a manner to divert precipitation away from the excavated area. Minimal infiltration of rainfall is expected. Any rainfall that does infiltrate the ground surface must migrate through clean backfill before reaching the residual hydrocarbons.

There is no source material at the ground surface, so direct contact of hydrocarbons with livestock and the populous is not likely.

In general, outside of the vulnerable area and alluvial valleys, bedrock material is generally encountered within 20 feet of the ground surface. Bedrock material in the San Juan Basin consists of interbedded sandstones, shales and clays. According to Freeze and Cherry, 1979, the hydraulic conductivity of the bedrock material are as follows:

Sandstone 10<sup>-9</sup> to 10<sup>-13</sup> cm/sec Shale 10<sup>-12</sup> to 10<sup>-16</sup> cm/sec Clay 10<sup>-12</sup> to 10<sup>-15</sup> cm/sec

Based on this information, the residual hydrocarbons should not migrate to groundwater.

Natural process (bioremediation) are degrading the residual hydrocarbon to carbon dioxide and water and will continue until the source is gone, therefore minimizing any impact to the environment.

Based on the above information, it is highly unlikely that any source material will impact groundwater or ever find an exposure pathway to affect human health and therefore El Paso Field Services Company (EPFS) requests closure of this pit location.



(SP3190) 03/16/94

GENERAL	Meter: 23043 Location: MADDOX WN FEDERAL #/ Operator #: 0286 Operator Name: CONOCO P/L District: KUTZ  Coordinates: Letter: H Section 13 Township: 30 Range: 13  Or Latitude Longitude  Pit Type: Dehydrator X Location Drip: Line Drip: Other:  Site Visit Date: 3.24.94 Run: 02 31		
NMOCD Zone: Inside   Land Type: BLM   State   Fee   Maps   Zone   Outside   Maps   Fee   Indian      Depth to Groundwater   Less Than 50 Feet (20 points)   So Ft to 99 Ft (10 points)   Greater Than 100 Ft (0 points)   Wellhead Protection Area : Is it less than 1000 ft from wells, springs, or other source fresh water extraction? , or ; Is it less than 200 ft from a domestic water source?   YES (20 points)   NO (0   Horizontal Distance to Surface Water Body   Less Than 200 Ft (20 points)   200 Ft to 1000 Ft (10 points)   Greater Than 1000 Ft (0 points)   Name of Surface Water Body   (Surface Water Body : Perennial Rivers, Major Wash, Streams, Carrigation Canals, Ditches, Lakes, Ponds)   TOTAL HAZARD RANKING SCORE:   O POINTS			
REMARKS	Remarks: Two PITS ON LOCATION. WILL CLOSE ONLY ONE. PIT IS DRY.  (SP3180) 93/16/		


<b>⊢</b> →
Z
$\subseteq$
⋖
LOCATIO
$\overline{}$
ب
$\rightarrow$
r .
Ξ
PIT
٦.
⋖
<u>ښ</u>
RIGINAL
-
$\simeq$
$\overline{}$

			Market Street, Square,
A TA		- Sales Marie	
ORIGINAL	11177	T // //	ATION
I I I TI I I I I I I I I I I I I I I I			ATTTEN
OIMUINAL		T AL SE .	A

Original Pit: a) Degrees from North 241 Footage to Wellhead 58

b) Degrees from North \_\_\_\_\_Footage to Dogleg \_\_\_\_\_

c) Length : \_\_\_\_\_\_ Width : \_\_\_\_\_\_ Depth : \_\_\_\_\_\_\_



STARTED TOKING PICTURES AT 3:05 P.M.

END DUMP

REMARKS

Completed By:

Signature

3.24.94

Date

# F\_LD PIT REMEDIATION/CLC JRE FORM

GENERAL	Meter: 73043 Location: Madaox WN Federal #1  Coordinates: Letter: H Section 13 Township: 30 Range: 13  Or Latitude Longitude  Date Started: 4-21-94 Area: 02 Run: 31
FIELD OBSERVATIONS	Sample Number(s): 18  Sample Depth: 4' Feet  Final PID Reading 455 PP PID Reading Depth 4' Feet  Yes No  Groundwater Encountered (1) (2) Approximate Depth Feet
CLOSURE	Remediation Method:  Excavation
- IKEMARKS	Remarks: Dug test tok to 4' Hit Sandstone Layer  Took PID Reading Closed pit.  Signature of Specialist: Henry Lean  (SP3191) 04/07/94



## FIELD SERVICES LABORATORY ANALYTICAL REPORT PIT CLOSURE PROJECT - Soil

## SAMPLE IDENTIFICATION

SAMPLE IDENTIFICATION									
	Field II	)		Lab ID					
SAMPLE NUMBER:	KDIP		946						
MTR CODE   SITE NAME:		11/3	NA						
SAMPLE DATE   TIME (Hrs):	4/7/	94 NIA	1015						
SAMPLED BY:	4~	72-94							
DATE OF TPH EXT.   ANAL.: DATE OF BTEX EXT.   ANAL.:		JIA	NIA COARSÉ SAND						
TYPE   DESCRIPTION:	Va		COAK	156 S/	4NU_				
REMARKS: _									
	F	RESULTS							
			<del></del>						
PARAMETER	RESULT	UNITS	DF Q M(g) V(ml)						
BENZENE		MG/KG							
TOLUENE		MG/KG							
ETHYL BENZENE		MG/KG							
TOTAL XYLENES		MG/KG			-				
	1.05/14/64	MG/KG							
TPH*(418.1): 1070	مسے بدنا	MG/KG			7.05	128			
	455	PPM							
HEADSPACE PID	93.3%	%							
PERCENT SOLIDS	TPH is by EPA Method	418.1 and BTEX is by	EPA Method 8020						
The Surrogate Recovery was at% for this sample All QA/QC was acceptable.									
Narrative:									

DF = Dilution Factor Used

> Perkin-Elmer Model 1600 FT-IR Analysis Report

\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*

~4/04/22 13:17

Sample identification 40854

Initial mass of sample, g

Volume of sample after extraction, ml = 3.000

Petroleum hydrocarbons, ppm 265.149

Net absorbance of hydrocarbons (2930 cm-1)

