

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency Musajo
Allottee _____
Lease No. 27142
11-22-42-202

SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

OCT 29 1957

U.S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

October, 1957

Well No. 1 Musajo is located 1000 ft. from N line and 660 ft. from E line of sec. 10
24 10 30N 10W 10W
(4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5200 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Pumped 25 sacks cement into 5' casing remaining in hole. (Sufficient to fill up 50' above perforations).

Set plug at 10' below surface, filled to surface with cement and set surface pipe extending four feet above surface.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Arizona Explorations, Inc.

Address 111 Madison Bldg.

Dallas 6, Texas

By

Title

Vice-President



