


District I
P.O. Box 1980, Hobbs, NM
District II
P.O. Drawer DD, Artesia, NM 88211
District III
1000 Rio Brazos Rd, Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

OK
SUBMIT 1 COPY TO
APPROPRIATE
DISTRICT OFFICE
AND 1 COPY TO
SANTA FE OFFICE

PIT REMEDIATION AND CLOSURE REPORT



Operator: Colt Resources
JN Exploration & Production LP Telephone: 406-248-2222
Address: P.O. Box 7167, Billings, Montana 59103
Facility or: FARNSWORTH GAS COM A1
Well Name
Location: Unit or Qtr/Qtr Sec B NWNE Sec 17 T 30N R 13W County SAN JUAN, New Mexico
Pit Type: Separator Dehydrator Other RESERVE PIT. OR Blowdown Pit.
Land Type: BLM , State , Fee X, Other

Pit Location: Pit dimensions: length 30, width 50, depth 4
(Attach diagram) Reference: wellhead X, other
Footage from reference: 250
Direction from reference: 90 Degrees X East North X
of
West South

Depth To Ground Water: Less than 50 feet (20 points)
(Vertical distance from 50 feet to 99 feet (10 points)
contaminants to seasonal Greater than 100 feet (0 Points) 10
high water elevation of ground water)

Wellhead Protection Area: Yes (20 points)
(Less than 200 feet from a private No (0 points) 0
domestic water source, or; less than 1000 feet from all other water sources)

Distance To Surface Water: Less than 200 feet (20 points)
(Horizontal distance to perennial 200 feet to 1000 feet (10 points)
lakes, ponds, rivers, streams, creeks, Greater than 1000 feet (0 points) 0
irrigation canals and ditches)

RANKING SCORE (TOTAL POINTS): 10

Date Remediation Started: 6.18.98 Dated Completed: 6.18.98

Remediation Method: Excavation Approx. cubic yards 0
(Check all appropriate sections) Landfarmed Insitu Bioremediation

Other No Action taken BEYOND 5pt. composite
Sample from 3' Below Pit Floor

Remediation Location: Onsite Offsite
(ie. landfarmed onsite, name and location of offsite facility)

General Description Of Remedial Action: FENCE & Pit berms remain
in place.

Ground Water Encountered: No X Yes Depth

Final Pit: Sample location 5 Pt. bottom Sample
Closure Sampling:
(if multiple samples, attach sample results and diagram of sample locations and depths)
Sample depth 3' Below Pit Floor
Sample date 6.18.98 Sample time 10:45

Sample Results
Benzene(ppm) ND
Total BTEX(ppm) ND
Field headspace(ppm) ND
TPH ND

Ground Water Sample: Yes No X (If yes, attach sample results)

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF
DATE 10.26.00
SIGNATURE Harold M. Brown PRINTED NAME Harold M. Brown
AND TITLE Geologist / Hydrogeologist

ENVIROTECH LABS

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

EPA METHOD 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons


Client:	J N Exploration	Project #:	98056-01
Sample ID:	Farnsworth G Com A1 @ 3'	Date Reported:	06-19-98
Laboratory Number:	D447	Date Sampled:	06-18-98
Chain of Custody No:	6127	Date Received:	06-18-98
Sample Matrix:	Soil	Date Extracted:	06-19-98
Preservative:	Cool	Date Analyzed:	06-19-98
Condition:	Cool and Intact	Analysis Requested:	8015 TPH


Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	ND	0.2
Diesel Range (C10 - C28)	ND	0.1
Total Petroleum Hydrocarbons	ND	0.2

ND - Parameter not detected at the stated detection limit.

References: Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Comments: La Plata Hwy. Pits. Blowdown Pit @ 3'.


Analyst


Review

ENVIROTECH LABS

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client:	J N Exploration	Project #:	98056-01
Sample ID:	Farnsworth G Com A1 @ 3'	Date Reported:	06-19-98
Laboratory Number:	D447	Date Sampled:	06-18-98
Chain of Custody:	6127	Date Received:	06-18-98
Sample Matrix:	Soil	Date Analyzed:	06-19-98
Preservative:	Cool	Date Extracted:	06-19-98
Condition:	Cool & Intact	Analysis Requested:	BTEX

Parameter	Concentration (ug/Kg)	Det. Limit (ug/Kg)
Benzene	ND	8.8
Toluene	ND	8.4
Ethylbenzene	ND	7.6
p,m-Xylene	ND	10.8
o-Xylene	ND	5.2
Total BTEX	ND	


ND - Parameter not detected at the stated detection limit.


Surrogate Recoveries:	Parameter	Percent Recovery
	Trifluorotoluene	96 %
	Bromofluorobenzene	96 %

References: Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA December 1996.

Method 8021B, Aromatic Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Comments: La Plata Hwy. Pits. Blowdown Pit @ 3'.


Analyst


Review

CHAIN OF CUSTODY RECORD

6127

Client / Project Name		Project Location		ANALYSIS / PARAMETERS																	
JN Exploration		La Plata Hwy Pds																			
Sampler: <i>Harcourt W. Brown</i>		Client No. 98056-01		Remarks																	
Sample No./ Identification	Sample Date	Sample Time	Lab Number	Sample Matrix	No. of Containers	8015 TPT	8021 BTAP	Analysis													
Farmington Glen #1 @ 3'	6.18.98	10:45	6447	Soil	1	✓	✓														
Miller B.1																					
Control CF #	6.18.98	10:05	6448	Soil	3	✓	✓	✓													
<i>Hold. (circled) Brought back to lab</i> <i>Good thru</i>																					
<table border="1"> <thead> <tr> <th colspan="3">Sample Receipt</th> </tr> <tr> <th>Received Intact</th> <th>Y</th> <th>N</th> </tr> </thead> <tbody> <tr> <td>Received Intact</td> <td>✓</td> <td></td> </tr> <tr> <td>Cool - Ice/Blue Ice</td> <td>✓</td> <td></td> </tr> </tbody> </table>										Sample Receipt			Received Intact	Y	N	Received Intact	✓		Cool - Ice/Blue Ice	✓	
Sample Receipt																					
Received Intact	Y	N																			
Received Intact	✓																				
Cool - Ice/Blue Ice	✓																				
Relinquished by: (Signature) <i>Harold W. Brown</i>		Date 6.18.98	Time 12:05	Received by: (Signature) <i>Adrian L. Ojeda</i>		Date 6.18.98	Time 12:05														
Relinquished by: (Signature)				Received by: (Signature)																	
Relinquished by: (Signature)				Received by: (Signature)																	

ENVIROTECH INC.

5796 U.S. Highway 64
Farmington, New Mexico 87401
(505) 632-0615