FORM C-103 (Rev 3-55)

NEW MEXICO OIL CONSERVATION COMMISSION

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Mandel Co.				# IU					
	Well No.	Unit L	.etter		Township	R	ange		
c State	1	<u> </u>			T 30N		R16W		
Pool				ľ	•	Tona			
unges.		T OF. ((hoch a	bbecheid		1 American			
				рртортіа		enlain):	 		
	_		пі јев	L	Other (Ex	pram,			
R	Remedial Worl	k							
ature and quantity	y of material:	s used, a	nd resu	lts obtai	ned.				
named we'll w	es plugg	ed in	the f	ollow	ing manne	rı			
lug was set	from 119	O' to	1403	with	20 sacks	of			
lug was set	£:cm su£	face t	o 10'	with	l sack o	of			
A 4' steel marker was set in the surface plug.									
on was aless	and I	eve led	_			1			
OU MES GIANT	MAN WITH T	.010204	•			र्ड कांग्र इ	$G_{\mathcal{F}_{2}}$.		
						10/2	1 1950		
						1	ON COLL		
							IST STIM!		
	Position	n			Company		- January Company		
FILL IN B	ELOW FOR	REMED	IAL W	ORK RE	PORTS ON	LY			
			ELL D	ATA	- · ·	 	ToI Date		
T D PBTD									
Tubing Depth		ľ	Oil String Diameter Oil String Depth						
l D				tenducing Formation(s)					
Open Hole Interval					todacing toumation(2)				
	RESU	LTS OF	WORK	OVER		 			
Oil Bandon		··			Production	GOR	Gas Well Potential		
BPD						Cubic feet/Bl			
			I here	by certi	fy that the in	formation given	above is true and comple		
OIL CONSERVATION COMMISSION			to the	to the best of my knowledge.					
Approved by Original Signed Emery C. Arnold				Name Attakoko N.					
3			Positi	on A	P. Rober	te, Jr., A	gent		
Supervisor Dist. # 3 Date AUG 2 3 1980				Company Carter & Mandel Co.					
	Pool Undes. THIS ins	Well No. State	Well No. State Pool Undes. Gallup THIS IS A REPORT OF: (comes of the comes of t	Well No. Unit Letter State Veil No. Unit Letter Pool THIS IS A REPORT OF: (Check a) Ins Casing Test and Cement Job Remedial Work Casing Test and Cement Job Casing Test and Ce	Mandel Co. State Well No. State Well No. Well No. Well No. Init Letter Section 16 Pool Undes. Gallup THIS IS A REPORT OF: (Check appropriants) Casing Test and Cement Job Remedial Work State Remedial Work State State Casing Test and Cement Job Remedial Work State State Casing Test and Cement Job Remedial Work State State Casing Test and Cement Job Remedial Work State State State Casing Test and Cement Job State State State Casing Test and Cement Job State St	Well No. Unit Letter Section Township State 1 16 T30N Pool Undes. Gallup THIS IS A REPORT OF: (Check appropriate block) Ins Casing Test and Cement Job Other (Ex. Remedial Work Institute and quantity of materials used, and results obtained. Institute and quantity of materials used, and results obtained. Institute and quantity of materials used, and results obtained. Institute and quantity of materials used, and results obtained. Institute and quantity of materials used, and results obtained. Institute and quantity of materials used, and results obtained. Institute and quantity of materials used, and results obtained. Institute and quantity of materials used, and results obtained. Institute and quantity of materials used, and results obtained. Institute and quantity of materials used, and results obtained. Institute and quantity of materials used, and results obtained. Institute and quantity of materials used, and results obtained. Institute and quantity of materials used, and results obtained. Institute and quantity of materials used, and results obtained. Institute and quantity of materials used, and results obtained. Institute and quantity of materials used, and results obtained. Institute and quantity of materials used, and results obtained. Institute and quantity of materials used, and results obtained. Institute and quantity of materials used, and results obtained. Institute and quantity of materials used, and results obtained. Institute and quantity of materials used, and results obtained. Institute and quantity of materials used, and results obtained. Institute and quantity of materials used, and results obtained. Institute and quantity of materials used, and results obtained. Institute and quantity of materials used, and results obtained. Institute and quantity of materials used, and results obtained. Institute and quantity of materials used, and results obtained. Institute and quantity of materials used, and results obtained. Institute and quantity of materials used, an	Mandel Co. Well No. Unit Letter Section Township Reserved Seate Township Remedial Work Sean Seate County Sean Juan		

STATE OF NEW	MEXICO
OIL CONSTRUCTION	COMMISSIO
r.ZT.C DISTRICT	OFFICE
NUMBER OF COP ES RECEIVE	
\$7 i	11
SANIA FE	7
Fire San	
E D OFFICE	
TRANSFORTER OH	
Proprietal Office	
UPERATUR	

•

•

•

.